HTA-E-SOP-001

Hy-Tec Industries

Safety Management System

"Uncontrolled Copy When Printed"

Pollution Incident Response Management Plan (PIRMP)

Austen Quarry

Revision:	Date:	Status:	Prepared/Reviewed by:
10	06.02.2023	Issued for use	D. Thiedeke

Status: APPROVED Owner: HSE Manager Doc: HTA-E-SOP-00	Rev: 0 Issued: 12/03/2019	Page 1 of 2
---	---------------------------	-------------

HTA-E-SOP-001

Hy-Tec Industries

"Uncontrolled Copy When Printed"

Pollution Incident Response Management Plan (PIRMP)

Contents

- 1. Element 21 (SMS extract)
- 2. Appendix 21A Environmental Incident Definition and Response Flow Chart
- 3. Appendix 21B Environmental Response Plan Drill Report
- 4. ABL-HSE-GSS-12-03 Emergency Response Contact Details
- 5. Appendix 4B Management Structure Register
- 6. Appendix 3B Mine Plan (Site Map)
- 7. Appendix 17B Hazardous Substance Register
- 8. Appendix 7K Risk Management Process
- 9. Appendix 7D Risk Assessment Tool
- 10. Appendix 8G Environmental Hazard Management Matrix
- 11. Appendix 7F Hazard Register/Principal Mine Hazard Register
- 12. Appendix 19B PPE Equipment Matrix
- 13. Appendix 1A Document control

Status: APPROVED	Owner: HSE Manager	Doc: HTA-E-SOP-001	Rev: 0	Issued: 12/03/2019	Page 2 of 2

ABL-HSE-GOS 22-SMS

Hy-Tec Industries

Safety Management System

"Uncontrolled Copy When Printed"

21. ENVIRONMENTAL INCIDENT RESPONSE-POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

21.1PURPOSE

C&A Hy-Tec Quarries have systems in place to ensure all environmental/pollution incidents and hazards are controlled and monitored in line with the relevant state legislation.

21.2 SCOPE

This element applies to all C&A Hy-Tec Quarry employees, contractors, sub-contractors and visitors to ensure that all individuals are aware of requirements with regards to environmental incident issues. This element is used in conjunction with ABL-HSE-GSS-11 for reporting. If a pollution incident occurs in the course of an activity, so that material harm to the environment (within the meaning of **Part 5.7** – **Duty to notify pollution incidents** - section 147 – NSW POEO Act) is caused or threatened, the person carrying on the activity must immediately implement the site's pollution incident response management plan in relation to the activity required by this Part and report any incident / incidents that cause or threaten material harm **Immediately** after becoming aware of the incident.

21.3 PROCEDURE

All hazards relating to human health or the environment will be described in the Environmental Hazard Management Matrix (Appendix 8G). The details of the pre-emptive action to be taken to minimize or prevent any risk of harm to human health or the environment arising out of the relevant activity will be recorded in a JHA (Appendix 7C) and/or a Risk Assessment (Appendix 7D). Risks will be minimised using the Risk Management Process (Appendix 7K).

An inventory of potential pollutants on the premises will be recorded in a Hazardous Substance Register (Appendix 17B). This register will also include the quantity and location of the pollutant.

A description of the safety equipment or other devices that are used to minimize the risks to human health or the environment and to contain or control a pollution incident are listed in the PPE Equipment Matrix (Appendix 19B) and Hazard Register (Appendix 7F).

The names, positions and contact details of key individuals at the quarry are kept in the Management Structure Register (Appendix 4B).

The contact details of each relevant authority are required to be available and displayed. Examples of required authorities are below:

- (a) EPA/OEH
- (b) Local Council
- (c) Local DPI office
- (d) Safe Work
- (e) Fire and Rescue
- (f) Water Catchment Authority
- (g) Ministry of Health
- (h) Department of Agriculture, Water and the Environment

A neighbourhood contact list will be maintained at the site. In an emergency incident, the appropriate neighbours will be contacted by the Quarry Manager or delegate and will be updated as required by the Quarry Manager / delegate. Constant communication such as 2-way radios, mobile phones and Business Communication (Toolbox) Meetings etc. (Appendix 6B) will be used as early warning mechanisms to communicate with site staff and management throughout the incident or other times.

Status: APPROVED	Owner: HSE Manager	Doc: ABL-HSE-GOS-22-SMS	Rev: 9.0	Issued: 15/01/2021	Page 1 of 2
------------------	--------------------	-------------------------	----------	--------------------	-------------

ABL-HSE-GOS 22-SMS

Hy-Tec Industries

Safety Management System

"Uncontrolled Copy When Printed"

An Environmental Incident Definition and Response Flow Chart (Appendix 21A) has been produced for guidance on the process of dealing with a pollution incident. "Pollution" means:

(a) water pollution, or

- (b) air pollution, or
- (c) noise pollution, or
- (d) land pollution.

Definition - "Pollution Incident" - means an incident or set of circumstances during or as a consequence of which there is or is likely to be a leak, spill or other escape or deposit of a substance, as a result of which pollution has occurred, is occurring or is likely to occur. It includes an incident or set of circumstances in which a substance has been placed or disposed of on premises, but it does not include an incident or set of circumstances involving only the emission of any noise.

The mine plan (Appendix 3B) will show the location of the premises with the property boundary and any other relevant detail.

The qualifications and training competencies of all employees will be recorded as required in the Training Register (Appendix 11F).

It is a legislative requirement for this plan to be tested and updated on an annual basis and within one month of an incident. To complete this requirement a Pollution Incident Response Drill Report (Appendix 21B) has been prepared. The checklist includes the major elements of the plan that require testing. This PIRMP is to be reviewed and updated as required at least annually to ensure that incident response systems are fully functioning and are ready to be implemented if an incident occurs. This requirement shall be listed as an action item and scheduled on the environmental compliance planner. Training records should be stored on site and in the Hy-Tec Intranet data base.

The plan will be controlled and reviewed in accordance with Element 5. Any changes will be recorded along with the date in the SMS Amendment Sheet (Appendix 1A).

21.4 REFERENCES

- Environmental Protection Act 1994
- Protection of the Environment Operations Act 1997
- <u>Protection of the Environment Operations (General) Amendment (Pollution Incident Response</u> <u>Management Plans) Regulation 2012</u>

Status: APPROVED	Owner: HSE Manager	Doc: ABL-HSE-GOS-22-SMS	Rev: 9.0	Issued: 15/01/2021	Page 2 of 2
------------------	--------------------	-------------------------	----------	--------------------	-------------



HTQY-P-FC-048

Hy-Tec Industries – Austen Quarry

"Uncontrolled Copy When Printed"

Appendix 21A

Environmental Incident Definition and Response Flow Chart

"pollution incident" means an incident or set of circumstances during or as a consequence of which there is or is likely to be a leak, spill or other escape or deposit of a substance, as a result of which pollution has occurred, is occurring or is likely to occur. It includes an incident or set of circumstances in which a substance has been placed or disposed of on premises, but it does not include an incident or set of circumstances involving only the emission of any noise.

Meaning of material harm to the environment

- (1) For the purposes of this Part:
 - (a) harm to the environment is material if:

(i) it involves actual or potential harm to the health or safety of human beings or to ecosystems that is not trivial, or

(ii) it results in actual or potential loss or property damage of an amount, or amounts in aggregate, exceeding \$10,000 (or such other amount as is prescribed by the regulations), and

(b) loss includes the reasonable costs and expenses that would be incurred in taking all reasonable and practicable measures to prevent, mitigate or make good harm to the environment.

(2) For the purposes of this Part, it does not matter that harm to the environment is caused only in the premises where the pollution incident occurs.

Appendix 21A

Environmental Incident Definition and Response Flow Chart



Adelaide Brighton

SAFETY MANAGEMENT SYSTEM

HTQY-E-SFT-024	Hy-Tec Industries – Austen Quarry			
Appendix 21B	"Uncontrolled Copy When Printed"	Environmental Re	sponse Plan Drill Report	
Site/Location:	Date of Drill / Environmental Iss	ue	· · ·	
Method Used for initiating response:				
Time of Environmental incident:	Was Management contacted?			
Was Incident contained?	Method/equipment used?			
Was regulatory Authority notified?	Name of reporting person?			
Name of regulatory authority reported to	Contact person at Reg. Authorit	y?		
Was incident adequately cleaned up?	Was waste disposed of correctl	y?		
Comments on the Drill / Environmental En	ergency:			
Corrective actions to be adopted as a resu	t of this Drill / Environmental Emergency	By whom	By Date	
Report Compiled by			Date	

Status: Approved	Owner: HSE Manager	Doc: HTQY-E-SFT-024	Rev: 0.0	Issued: 20/05/2014	Page 1 of 1
	0				

Group HSE System Standard

Adelaide Bright

ABL-HSE-GSS-12-03

EMERGENCY RESPONSE CONTACT – AUSTEN QUARRY

"Uncontrolled Copy When Printed"

	E EMERGENCY RE	XTERNAL SPONSE ORGAN	ISATIONS
Service	Emergency Contact	General Enquiry	Address
Ambulance	000		21/15 Railway Pde, Lithgow
Department of Industry – Water	02 9338 6600	02 9338 6600	www.industry.nsw.gov.au/water
Department Planning & Environment	1300 305 695		www.planning.nsw.gov.au
Depart. P & E – Resources Regulator	1300 814 609		www.resourcesregulator.nsw.gov.au
Doctor – Coal Services	N/A	02 6350 1050	3 Proto Ave, Lithgow
E.P.A	131 555		
Fire Brigade	000	02 6353 1862	58 Cook St Lithgow
Lithgow Hospital	000	02 6350 2300	Great Western Hwy Lithgow.
Lithgow Council		02 6354 9999	180 Mort St, Lithgow
Poisons Information Centre	N/A	13 11 26	www.poisonsinfo.nsw.gov.au
Police	000	02 6352 8399	244 Mort St Lithgow
Ministry of Health		02 9391 9000	www.health.nsw.gov.au
SafeWork NSW	13 10 50	13 10 50	contact@safework.nsw.gov.au
State Emergency Service	13 25 00	N/A	Lithgow

If any emergency service (**Police, Fire or Ambulance**) is called to site, a nominated employee must meet the response team at the front gate (391 Jenolan Caves Road) to the Quarry and escort them to the required location.

List of Neighbourhood contacts to be maintained at the Quarry – **For privacy reasons, this list is not to be published.**

Status: FINAL	Department: Group HSE	Doc: ABL-HSE-GSS-12-03	Rev: 1.0	Issued:	Page 1 of 2

Adelaide Bright

ABL-HSE-GSS-12-03

2-03 EMERGENCY RESPONSE CONTACT – AUSTEN QUARRY





Helicopter Directions For emergency purposes

Latitude & Longitude 33°34'15'' South 150°09'05'' East – Carpark opposite Quarry Office

Being 33 degrees, 34 minutes and 15 seconds south / 150 degrees, 9 minutes and 5 seconds East

Status: FINAL	Department: Group HSE	Doc: ABL-HSE-GSS-12-03	Rev: 1.0	Issued:	Page 2 of 2





Hy-Tec Industries – Austen Quarry

Appendix 4B

"Uncontrolled Copy When Printed"

Register of persons occupying positions in the Management Structure

Position	Name	Start Date	Responsible for activating Incident Response Plan (Y/N)	Authority to Notify (Y/N)	Responsible to Manage Pollution Incident (Y/N)	Finish Date
Chief Operating Officer – Concrete, Aggregates & Masonry	Andrew Dell (02) 9751 7115 / 0417 607 450	N/A	Ν	Y	N	
National Planning & Development Manager	Darryl Thiedeke (02) 9751 7130 / 0409 652 022	N/A	Ν	Y	N	
Group Manager – Health, Safety & Environment	Steven De Musso 0439 740 293	N/A	Ν	Y	N	
General Manager NSW	David Cilento (02) 9751 7143 / 0418 162 498	N/A	Ν	Y	N	
Business Partner Health and Safety – CAM (NSW)	Joe Perulero 0479 188 381	N/A	Ν	Y	N	
Manager – Quarry Operations NSW	Ethan Pettiford 0437 147 778	March 2013	Y	Y	N	
Quarry Manager	Craig McDonald 0405 123 700	June 2006	Υ	Y	Y	
Quarry Supervisor	Michael Greenwood 0418 678 323	April 2021	Y	Ν	Y	
Quarry Supervisor	Luke McNamara 0429394197	May 2022	Y	N	Y	
Lab Technician	Michael Fry 0451146306	August 2022	Y	N	N	
Administration	Lisa Cullen 0408 279 462	March 2020	Y	N	N	





Page 2 of 2

HTQY-S-HSE-072

Hy-Tec Industries – Austen Quarry

"Uncontrolled Copy When Printed"

Appendix 4B

Register of persons occupying positions in the Management Structure

Primary Plant Operator	Brett Barker	August 2022	Y	N	Ν	
Quarry Worker	John Ray	September 2022	Y	N	N	
Quarry Worker	Bob Rowlandson	November 2007	Y	N	N	
Quarry Worker	Alan Eckford	Jan 2008	Y	N	N	
Quarry Worker	Peter Ray	May 2008	Y	N	Ν	
Quarry Worker	Duncan Stanfield	June 2021	Y	N	Ν	
Quarry Worker	Chris O'Malley	August 2010	Y	N	Ν	
Quarry Worker	Dylan Holland	June 2021	Y	N	N	
Quarry Worker	Sean Markwick	December 2022	Y	N	Ν	
Quarry Worker	Mark Cullen	Jan 2017	Y	N	N	
Quarry Worker	Neil Gearside	August 2022	У	N	N	
Quarry Worker	Robert Sheather	Jan 2023	Y	N	N	
Quarry Worker	Brendan Neaves	Sept 2017	Y	N	N	
Quarry Worker	Shannon Rhodes	Jul 2018	Y	N	N	
Quarry Worker	Craig Silcock	Aug 2018	Y	N	N	
Sales Representative	Anna Antonis (0439103570)	N/A	Y	Ν	Ν	
Sales Representative	Peter Mckee (0417 452 098)	N/A	Y	N	Ν	
Electrician	Paul Taylor (0409 514 993)	N/A	Y	N	N	
Plant Maintenance	Mark Gracey (0417727227)	N/A	Y	N	N	

Status: Approved	Owner: Group HSE	Doc: HTQY-S-HSE-072	Rev: 1.0	Issued: 27 May 2013



Adelaide Bright



Hy-Tec Industries - Austen Quarry

"Uncontrolled Copy When Printed"

Appendix 3B – MINE PLAN / EQUIPMENT LOCATION and EMERGENCY RESPONSE



Thiedeke

Status: APPROVED Owner: HSE Mar	ager Doc: HTQY-S-HSE-069	Rev: 0.0	Issued: 11 Sep 2012	Page 1 of 3	
---------------------------------	--------------------------	----------	---------------------	-------------	--



"Uncontrolled Copy When Printed"





Call Point

Weigh Bridge

Generator

- Lunch Room

Bottom Plant

Top Plant ·

Conveyer

Status: APPROVED	Owner: HSE Manager	Doc: HTQY-S-HSE-069	Rev: 0.0	Issued: 11 Sep 2012	Page 2 of 3
	Ŭ				0



Adelaide Bright

HTQY-S-HSE-069

Hy-Tec Industries - Austen Quarry

"Uncontrolled Copy When Printed"

THINK ACT SAFELY

EMERGENCY CONTACT DETAILS: Plant Manager - 0418 292 843 or Dial 000

EMERGENCY RESPONSE

KEEP CALM FOLLOW THE PLANT SUPERVISOR'S INSTRUCTIONS

ALL VISITORS & CONTRACTORS MUST REPORT DIRECTLY TO THE SITE OFFICE.

NO UNAUTHORISED ACCESS IS PERMITTED!











First Aid Personnel

Rodd Welsh, Craig McDonald, Stewart Gunn, Peter Horner.

Company Doctor

Coal Services Lithgow - 6350 1050

General Contact &/or Complaints, please ring 02 63550268.

FIRST EMERGENCY STEPS

ASSESS

- Does a danger still exist?
- ALERT Phone emergency services
- ASSIST • Provide
 - Provide First Aid and comfort
 Direct emergency services

What are the injuries?What help is required?

EVACUATION PROCEDURE

- Proceed via safest route to the EMERGENCY ASSEMBLY AREA
- 2 Assist mobility impaired personnel as requested.

Assist mobility impaired



3

Ensure your presence is noted at the Emergency Assembly Area.











- Fire Extinguisher
- First Ald Kit
- Stop / Give-Way
- Call Point
- 🔗 No Entry
- → General Traffic Direction
- TIp Off Area



Emergency Evacuation Area

Status: APPROVED Owner:	: HSE Manager	Doc: HTQY-S-HSE-069	Rev: 0.0	Issued: 11 Sep 2012	Page 3 of 3
-------------------------	---------------	---------------------	----------	---------------------	-------------



ChemAlert's distinct colour rating system to allows for an easy visual interpretation of the hazard level associated with chemical substances.

The three distinct colours and their meaning are as follows:

Low Health Hazard with normal use.

User Check List:

- Read the SDS and ChemAlert report thoroughly before using the product
- Clarify any concerns you might have about the product or its application
- If PPE is specified, are workers experienced in its use?



Moderate Health Hazard with normal use.

User Check List

- Read the SDS and ChemAlert report thoroughly before using the product
- Clarify any concerns you might have about the product or its application
- Is there a safer substitute?
- Is the area adequately ventilated?
- Does the area of application need to be isolated?
- Is air monitoring required to evaluate exposure levels?
- Have safe work practices or procedures been established?
- If PPE is specified, are workers experienced in its use?



High Health Hazard with normal use.

User Check List:

- Read the SDS and ChemAlert report thoroughly before using the product.
- Clarify any concerns you might have about the product or its application.
- Does the product need to be used (can the product or task be eliminated)?
- Is there a safer substitute?
- Is the area adequately ventilated?
- Does the area of application need to be isolated?

- Is there a first aid officer or nurse available?
- Is air monitoring required to evaluate exposure levels?
- Have safe work practices or procedures been established?
- Are medical records kept for those handling this product?
- If PPE is specified, are workers experienced in its use?



Developed and supported by

Australia: 1800 555 477 New Zealand: 0800 889 225 International: +61 8 9322 1711



www.chemalert.com chemalert@rmt.com.au



(Location Name: Adbri Limited/ CONCRETE & AGGREGATES/ NEW SOUTH WALES/ HY-TEC/ AUSTEN QUARRY, Child Locations

Included)

a	Product Name				Supplier (Emergency Contact)				
Stock Number	Hazardous	Dangerous Good	UN number	Packing Group	Hazchem Code	Status	In Stock Inventory	Risk Assessment	SDS Date
			•		-	-	•	-	•
2423	298 ASPHALT EMULS	ION		-	WESTERN COLLOID S	S.C., INC. (1-323-231	-8292)		
	Yes	No	-	-	-	None	Yes	-	07-Oct-2015
2388	636-LINE BRITISH PAI	NTS H2O ENAMEL SEM	IGLOSS		DULUX GROUP (AUST	RALIA) PTY LTD (1	800 220 770/ 0800 2	220 770)	
	Yes	No	-	-	-	None	Yes	-	16-Jul-2021
2387	637-LINE BRITISH PAI	NTS H2O ENAMEL GLOS	SS		DULUX GROUP (AUST	RALIA) PTY LTD (1	800 220 770/ 0800 2	220 770)	
	No	No	-	-	-	None	Yes	-	14-Apr-2020
569	ACETYLENE (DISSOL)	VED)			AIR LIQUIDE AUSTRAI	LIA LIMITED (1800 8	300 055, 1800 812 5	88)	
	Yes	DG 2.1	UN 1965	-	2YE	None	Yes	-	07-Apr-2022
2074	ADBLUE				AUSBLUE (1300 287 2	58)			
	No	No	-	-	-	None	Yes	-	05-Oct-2020
1773	AIR TOOL OIL				GULF WESTERN OIL ((02) 9673 9600/ 13 1	1 26)		
	No	No	-	-	-	None	Yes	-	30-Sep-2020
2107	AJAX SPRAY N WIPE A	ANTIBACTERIAL ALL PU JS	JRPOSE CLEANER SPR	AY APPLE	COLGATE-PALMOLIVE	E PTY LTD ((02) 903	7 2994)		
	Yes	No	-	-	-	None	Yes	-	23-May-2018
2329	ALPHA SP 150				CASTROL AUSTRALIA	PTY LTD ((02) 8014	4 4558; 1800 141 47	(4)	•
	No	No	-	-	-	None	Yes	-	23-Feb-2022
941	ALPHA SP 220				CASTROL AUSTRALIA	PTY LTD ((02) 8014	4 4558; 1800 141 47	(4)	•
	No	No	-	-	-	None	Yes	-	28-Feb-2022
2400	ALPHASYN EP 150				CASTROL AUSTRALIA	PTY LTD ((02) 8014	4 4558; 1800 141 47	(4)	
	No	No	-	-	-	None	Yes	-	02-Jul-2019
2401	ALPHASYN EP 220				CASTROL AUSTRALIA	PTY LTD ((02) 8014	4 4558; 1800 141 47	(4)	•
	No	No	-	-	-	None	Yes	-	02-Jul-2019
2405	ALPHASYN EP 460				CASTROL AUSTRALIA	PTY LTD ((02) 8014	4 4558; 1800 141 47	(4)	•
	No	No	-	-	-	None	Yes	-	02-Jul-2019
1792	AMMONIUM NITRATE				ORICA AUSTRALIA PT	Y LTD (1800 033 11	1)		•
	Yes	DG 5.1	UN 1942	PG III	1Y	None	Yes	-	09-Nov-2021
2397	AMPLIFY DIESEL				AMPOL AUSTRALIA PI	ETROLEUM PTY LT	D (FORMERLY CAL	TEX AUSTRALIA) (1800 033 111)
	Yes	DG 9	UN 3082	PG III	•3Z	None	Yes	-	15-Oct-2020



(Location Name: Adbri Limited/ CONCRETE & AGGREGATES/ NEW SOUTH WALES/ HY-TEC/ AUSTEN QUARRY, Child Locations

Included)

01	Product Name				Supplier (Emergency Contact)				
Number	Hazardous	Dangerous Good	UN number	Packing Group	Hazchem Code	Status	In Stock Inventory	Risk Assessment	SDS Date
			ł	- I		•		•	
1742	ARMORALL				ENVIRO CHEMICALS	(AUSTRALIA) PTY L	TD (1800 033 111)		
	No	No	-	-	-	None	Yes	-	01-Jan-2022
2395	AUTOCHEM HEAVY D	UTY ENGINE DEGREAS	ER		CHEMTOOLS PTY LTE	0 (1300 738 250/ 13	11 26)		
	Yes	No	-	-	-	None	Yes	-	31-Jul-2020
497	AUTOMOTIVE DIESEL	. FUEL			AMPOL AUSTRALIA P	ETROLEUM PTY LT	D (FORMERLY CAL	TEX AUSTRALIA) (1800 033 111)
	Yes	No	-	-	-	None	Yes	-	23-Jun-2021
2340	BP KOMATSU HYDRA	ULIC OIL 46			KOMATSU AUSTRALIA	A (+61 2 9795 8222)			
	No	No	-	-	-	Approved	Yes	-	11-Jan-2019
2392	BP KOMATSU LITHIUN	MEP GREASE G2-LI			KOMATSU AUSTRALIA	A (+61 2 9795 8222)			
	No	No	-	-	-	None	Yes	-	27-Jun-2018
836	BRAKE AND CLUTCH	FLUID			AMPOL AUSTRALIA P	ETROLEUM PTY LT	D (FORMERLY CAL	_TEX AUSTRALIA) (1800 033 111)
	No	No	-	-	-	None	Yes	-	27-May-2021
1797	BULK CENTRA PRODU	CENTRA PRODUCTS				TY LTD (1800 033 11	1)		
	Yes	DG 1.1D	UN 0241	-	E	None	Yes	-	17-Feb-2021
2389	C4 HYDRAULIC 10W				GULF WESTERN OIL (((02) 9673 9600/ 13	11 26)		
	No	No	-	-	-	None	Yes	-	31-May-2018
722	CARBON DIOXIDE (GA	AS & LIQUID)		·	CHUBB FIRE & SECUR	RITY AUSTRALASIA	(1300 369 309)		
	Yes	DG 2.2	UN 1044	-	2	None	Yes	-	16-Dec-2022
2330	CASTROL CARECLEA	N LIME	•	ł	CASTROL AUSTRALIA	A PTY LTD ((02) 801	4 4558; 1800 141 47	(4)	
	Yes	No	-	-	-	None	Yes	-	24-Jan-2019
2419	CASTROL MINE GREA	ASE			CASTROL AUSTRALIA	A PTY LTD ((02) 801	4 4558; 1800 141 47	(4)	
	No	No	-	-	-	None	Yes	-	20-Jun-2021
2331	CASTROL MULTIPURE	POSE DEGREASER			CASTROL AUSTRALIA	A PTY LTD ((02) 801	4 4558; 1800 141 47	(4)	
	Yes	No	-	-	-	None	Yes	-	06-Jan-2022
2193	CASTROL PREMIUM (COOL PLUS 50	1	-	CASTROL AUSTRALIA	A PTY LTD ((02) 8014	4 4558; 1800 141 47	(4)	
	Yes	No	-	-	-	None	Yes	-	29-Jul-2021
237	CASTROL PREMIUM H	HEAVY DUTY	I	4	CASTROL AUSTRALIA	A PTY LTD ((02) 801-	4 4558; 1800 141 47	(4)	
	No	No	-	-	-	None	Yes	-	29-Jun-2021
194	CASTROL RX SUPER	15W-40		•	CASTROL AUSTRALIA	A PTY LTD ((02) 801	4 4558; 1800 141 47	/4)	
	No	No	-	-	-	Approved	Yes	-	15-May-2018



(Location Name: Adbri Limited/ CONCRETE & AGGREGATES/ NEW SOUTH WALES/ HY-TEC/ AUSTEN QUARRY, Child Locations

Included)

01	Product Name				Supplier (Emergency Contact)				
Number	Hazardous	Dangerous Good	UN number	Packing Group	Hazchem Code	Status	In Stock Inventory	Risk Assessment	SDS Date
			ł						
2334	CASTROL TECTION 1	5W-40	1		BP LUBRICANTS USA	INC. (1 (800) 447-87	735, Outside the US:	+1 703-527-3887 (CHEMTREC))
	No	No	-	-	-	None	Yes	-	04-Sep-2019
848	CASTROL TFC 410				CASTROL AUSTRALIA	A PTY LTD ((02) 801	4 4558; 1800 141 47	(4)	
	No	No	-	-	-	None	Yes	-	29-Jan-2021
1924	CASTROL TFC 430				CASTROL AUSTRALIA	A PTY LTD ((02) 801	4 4558; 1800 141 47	(4)	
	No	No	-	-	-	None	Yes	-	20-Oct-2020
2098	CASTROL TFC 450				CASTROL AUSTRALIA	A PTY LTD ((02) 801	4 4558; 1800 141 47	(4)	
	No	No	-	-	-	None	Yes	-	20-Oct-2020
1879	CHUBB ABE DRY CHE	MICAL POWDER FIRE E	XTINGUISHER		CHUBB FIRE & SECUR	RITY AUSTRALASIA	(1300 369 309)		
	Yes	DG 2.2	UN 1044	-	-	None	Yes	-	16-Dec-2022
2413	CHUBB BE DRY CHEM	AICAL POWDER FIRE EX	TINGUISHER		CHUBB FIRE & SECUR	RITY AUSTRALASIA	(1300 369 309)	•	
	Yes	DG 2.2	UN 1044	-	-	None	Yes	-	16-Dec-2022
2412	CHUBB CLASS-D FIRE	EXTINGUISHER		•	CHUBB FIRE & SECUR	RITY AUSTRALASIA	(1300 369 309)		
	Yes	DG 2.2	UN 1044	-	-	None	Yes	-	23-Mar-2018
2415	CHUBB ECO FF FOAM	FIRE EXTINGUISHER			CHUBB FIRE & SECUR	RITY AUSTRALASIA	(1300 369 309)		
	Yes	DG 2.2	UN 1044	-	-	None	Yes	-	16-Dec-2022
2416	CHUBB F3 FOAM MOE	BILE FIRE EXTINGUISHE	R		CHUBB FIRE & SECUR	RITY AUSTRALASIA	(1300 369 309)	•	
	Yes	DG 2.2	UN 1044	-	-	None	Yes	-	14-May-2018
2414	CHUBB FOAM FIRE EX	XTINGUISHER			CHUBB FIRE & SECUR	RITY AUSTRALASIA	(1300 369 309)	•	
	Yes	DG 2.2	UN 1044	-	-	None	Yes	-	PRODUCT OBSOLETE
2361	CLEANER JIF 375ML F	REGULAR			OFFICEMAX NEW ZEA	ALAND LIMITED (+6	4 800 700 112/ +61 3	3 9573 3188)	•
	Yes	No	-	-	-	None	Yes	-	01-Nov-2019
2410	COMPANION				SST AUSTRALIA PTY	LTD (1800 638 556)	•		1
	Yes	DG 8	UN 1760	PG II	2X	None	Yes	-	16-Aug-2022
1791	CORDTEX DETONATI	NG CORDS			ORICA AUSTRALIA PI	TY LTD (1800 033 11	1)		4
	Yes	DG 1.1D	UN 0065	-	E	None	Yes	-	27-Jul-2022
2364	DETTOL HAND SANIT	ISER		•	RB (HYGIENE HOME)	AUSTRALIA PTY LT	TD (13 11 26 (PIC))		1
	Yes	DG 3	UN 1170	PG III	•2Y	None	Yes	-	13-Apr-2020
2066	DETTOL LIQUID HAND) WASH			RB (HYGIENE HOME)	AUSTRALIA PTY LT	TD (13 11 26 (PIC))		
	Yes	No	-	-	-	None	Yes	Available	14-Oct-2019



(Location Name: Adbri Limited/ CONCRETE & AGGREGATES/ NEW SOUTH WALES/ HY-TEC/ AUSTEN QUARRY, Child Locations

Included)

a , 1	Product Name				Supplier (Emergency Contact)				
Stock Number	Hazardous	Dangerous Good	UN number	Packing Group	Hazchem Code	Status	In Stock Inventory	Risk Assessment	SDS Date
	-		ļ.			F			
2391	DY-MARK HEAVY DUT	Y DEGREASER 400G			DY-MARK AUSTRALIA	((07) 3327 3099)			
	Yes	DG 2.1	UN 1950	-	2YE	None	Yes	-	01-Nov-2019
2393	DY-MARK ZINC GUAR	D SILVER ZINC			DY-MARK AUSTRALIA	((07) 3327 3099)			
	Yes	DG 2.1	UN 1950	-	2YE	None	Yes	-	01-Nov-2019
1187	EXEL DETONATORS (1.1B PACKAGING)			ORICA AUSTRALIA PTY LTD (1800 033 111)				
	Yes	DG 1.1B	UN 0360	-	E	None	Yes	-	11-Apr-2018
2386	GALMET SPRAYPAINT	FAEROSOL (ALL COLOU	IRS EXCEPT SILVER)		ITW POLYMERS & FLU	JIDS PTY LTD (1800) 385 556 / 0438 465	5 960/ 1800 039 008/	(03) 9573 3112)
	Yes	DG 2.1	UN 1950	-	2YE	None	Yes	-	01-Nov-2019
2411	GASSER 2, GASSIT, U	GS 400 SERIES GASSE	R (UNDERGROUND GA	SSER)	ORICA AUSTRALIA PT	TY LTD (1800 033 11	1)		
	Yes	No	-	-	-	None	Yes	-	27-Feb-2019
870	GLEN 20 ALL IN ONE S	SPRAY DISINFECTANT -	ALL SCENTS		RB (HYGIENE HOME)	AUSTRALIA PTY L1	D (13 11 26 (PIC))		•
	Yes	DG 2.1	UN 1950	-	2YE	None	Yes	-	23-Jan-2020
2359	HARPIC LIQUID FRES	H POWER – TROPICAL E	BLOSSOM	•	RB (HYGIENE HOME) AUSTRALIA PTY LTD (13 11 26 (PIC))				•
	Yes	No	-	-	-	Approved	Yes	-	31-Jan-2020
207	HHS2000		•	·	WURTH AUSTRALIA F	PTY LTD (1300 657 7	65/ 13 11 26)		•
	Yes	DG 2.1	UN 1950	-	2YE	None	Yes	-	20-Sep-2021
2409	HOT DEVIL BUTANE			·	LN MARKETING P/L (0	3 9775 0713)			•
	No	DG 2.1	UN 1057	-	2W	None	Yes	-	31-May-2018
2332	HYSPIN AWH-M 32		-	·	CASTROL AUSTRALIA	A PTY LTD ((02) 801	4 4558; 1800 141 47	(4)	•
	No	No	-	-	-	None	Yes	-	27-Nov-2020
2333	HYSPIN AWS 46			•	CASTROL AUSTRALIA	A PTY LTD ((02) 801	4 4558; 1800 141 47	(4)	•
	No	No	-	-	-	None	Yes	-	21-Jul-2022
816	INOX-MX3 AEROSOL				CANDAN INDUSTRIES	6 PTY LTD ((07) 557	4 8205)		•
	Yes	DG 2.1	UN 1950	-	2YE	None	Yes	-	28-Feb-2022
917	KEROSENE			•	GLENDALE PACKAGI	NG PTY LTD (0401 6	699 204)		
	Yes	DG 3	UN 1223	PG III	3Y	None	Yes	-	30-Jun-2019
1999	KOMATSU AXLE OIL A	XO80			BP AUSTRALIA PTY L	TD (1800 14 14 74 w	vithin Australia or +6	1 2 8014 4558)	
	No	No	-	-	-	None	Yes	-	<u>17-Jan-2018</u>
1998	KOMATSU EO15W40-E	DH	•		BP AUSTRALIA PTY L	TD (1800 14 14 74 w	vithin Australia or +6	1 2 8014 4558)	
	Yes	No	-	-	-	None	Yes	-	12-Jul-2021



(Location Name: Adbri Limited/ CONCRETE & AGGREGATES/ NEW SOUTH WALES/ HY-TEC/ AUSTEN QUARRY, Child Locations

Included)

(Sort By: Product Name, Filter By: None)

Otrach	Product Name				Supplier (Emergency Contact)				
Number	Hazardous	Dangerous Good	UN number	Packing Group	Hazchem Code	Status	In Stock Inventory	Risk Assessment	SDS Date
	-		ł			I	•	Į.	
2399	KOMATSU EO15W40-I	Н			KOMATSU AUSTRALIA	A (+61 2 9795 8222)			
	No	No	-	-	-	None	Yes	-	27-Jun-2018
2402	KOMATSU GENUINE E	ENGINE COOLANT (CON	CENTRATE)		KOMATSU AMERICA (CORP. (+1 352 323 3	3500)		
	Yes	DG 9	UN 3082	PG III	•3Z	None	Yes	-	07-Oct-2020
2407	KOMATSU GENUINE H	HYDRAULIC OIL HO-MVK	K EX		KOMATSU LTD (+81 3	5561 2952; +81 3 5	561 107 8414)		
	No	No	-	-	-	None	Yes	-	01-Jul-2019
1467	KOMATSU HYDRAULI	C OIL 46			CASTROL AUSTRALIA	A PTY LTD ((02) 801	4 4558; 1800 141 47	(4)	
	No	No	-	-	-	None	Yes	Available	11-Feb-2020
2406	KOMATSU HYPER GR	EASE G2-TE			KOMATSU AUSTRALIA	A (+61 2 9795 8222)			
	Yes	No	-	-	-	None	Yes	-	02-Nov-2020
2403	KOMATSU POWERTR	AIN OIL 30			KOMATSU AUSTRALIA	A (+61 2 9795 8222)			
	No	No	-	-	-	None	Yes	-	11-Jan-2019
1997	KOMATSU POWERTR	AIN OIL TO-10	•		CASTROL AUSTRALIA	N PTY LTD ((02) 801	4 4558; 1800 141 47	(4)	-1
	No	No	-	-	-	None	Yes	-	29-Jan-2021
1206	KOMATSU POWERTR	AIN OIL TO-30			BP AUSTRALIA PTY L	TD (1800 14 14 74 w	vithin Australia or +6	1 2 8014 4558)	
	No	No	-	-	-	None	Yes	Available	02-Nov-2020
2408	LECTRA CLEAN (AER	OSOL) (POST 1 JULY 20	18)		CRC INDUSTRIES (AU	IST) PTY LIMITED (13 11 26 (PIC))		
	Yes	DG 2.2	UN 1950	-	2YE	None	Yes	-	PRODUCT OBSOLETE
2382	LUDOWICI EZITROWE	L PART A	•		FLSMIDTH (1800 039 0)08)			
	Yes	DG 6.1	UN 2206	PG III	2X	None	Yes	-	<u>20-Nov-2013</u>
2383	LUDOWICI EZITROWE	L PART B		·	FLSMIDTH (1800 039 0	008)			•
	Yes	No	-	-	-	None	Yes	-	<u>20-Nov-2013</u>
2417	MEGAPOXY 108 - PAR	RT A			VIVACITY ENGINEERI	NG PTY LTD ((02) 9	875 3044)		
	Yes	DG 9	UN 3082	PG III	•3Z	None	Yes	-	<u>16-Jan-2018</u>
2418	MEGAPOXY 108 - PAR	RT B	•		VIVACITY ENGINEERI	NG PTY LTD ((02) 9	875 3044)	*	-
	Yes	DG 8	UN 2289	PG III	2X	None	Yes	-	<u>16-Jan-2018</u>
2394	MOLYTEC NON-CHLO	RINATED BRAKE CLEAN	IER		MOLYTEC AUSTRALIA	A P/L (1300 452 355))		•
	Yes	DG 2.1	UN 1950	-	2YE	None	Yes	-	15-Nov-2022
159	MOLYTEC ZINC COTE				MOLYTEC AUSTRALIA	A P/L (1300 452 355))		
	Yes	DG 2.1	UN 1950	-	2YE	None	Yes	-	15-Nov-2022

Company - ADELAIDE BRIGHTON LIMITED User - NOLOGON



(Location Name: Adbri Limited/ CONCRETE & AGGREGATES/ NEW SOUTH WALES/ HY-TEC/ AUSTEN QUARRY, Child Locations

Included)

	Product Name				Supplier (Emergency Contact)				
Number	Hazardous	Dangerous Good	UN number	Packing Group	Hazchem Code	Status	In Stock Inventory	Risk Assessment	SDS Date
			ł						•
2424	NORTHFORK TOILET	CLEANER	1		ACCO BRANDS AUST	RALIA PTY LTD (13	11 26 (Poisons Infor	mation Centre))	T
	Yes	No	-	-	-	None	Yes	-	23-Apr-2021
2362	NORTHFORK TOILET	RIM FRESHENER	1		ACCO BRANDS AUST	RALIA PTY LTD (13	11 26 (Poisons Infor	mation Centre))	t
	No	No	-	-	-	None	Yes	-	02-Dec-2022
2396	OSI VP275 MULTIPUR	POSE SILICONE SEALA	NT		HENKEL AUSTRALIA F	PTY LTD (1800 032 3	379)		
	Yes	No	-	-	-	None	Yes	-	09-Sep-2021
2365	OUST 3IN1 FROM GLADE HOSPITAL GRADE DISINFECTANT AEROSOL - OUTDOOR SCENT				S.C. JOHNSON & SON	I PTY. LTD. (AU) (13	11 26 (Poisons Info	rmation Centre)/ (02	9428 9111)
	Yes	DG 2.1	UN 1950	-	2YE	None	Yes	-	09-Nov-2021
570	OXYGEN, ALIGAL 3, L	ASAL 2003			AIR LIQUIDE AUSTRA	LIA LIMITED (1800 8	300 055, 1800 812 5	88)	·
	Yes	DG 2.2 / 5.1	UN 1072	-	2S	None	Yes	-	21-Oct-2021
2363	PALMOLIVE ANTIBAC	TERIAL DISHWASHING I	LIQUID LEMON		COLGATE-PALMOLIVE	E PTY LTD ((02) 903	7 2994)		
	Yes	No	-	-	-	None	Yes	-	PRODUCT OBSOLETE
1186	PENTEX BOOSTERS				ORICA AUSTRALIA PT	Y LTD (1800 033 11	1)		
	Yes	DG 1.1D	UN 0042	-	E	None	Yes	-	20-Apr-2022
2425	PINE O CLEEN MULTI	PURPOSE CLEANER TR	IGGER CRISP APPLE		RB (HYGIENE HOME) AUSTRALIA PTY LTD (13 11 26 (PIC))				
	Yes	No	-	-	-	None	Yes	-	14-Feb-2020
2384	RAPIDSTICK PITBULL	201 LOW MODULUS HY	BRID SEALANT		CHEMTOOLS PTY LTE	0 (1300 738 250/ 13	11 26)		
	Yes	No	-	-	-	None	Yes	-	31-Aug-2018
1007	SEPTONE PROTECTA	GRIT			ITW AAMTECH AUSTR	RALIA (1800 039 008	3)		
	No	No	-	-	-	None	Yes	-	01-Nov-2019
2385	SHELL GADUS S2 V10	00 3			VIVA ENERGY AUSTR	ALIA LTD (1800 651	818/ 13 11 26)		•
	No	No	-	-	-	None	Yes	-	05-Jan-2021
2404	SHELL OMALA OIL F	460 (USA)		VIVA ENERGY AUSTR	ALIA LTD (1800 651	818/ 13 11 26)			
	No	No	-	-	-	None	Yes	-	20-Mar-2020
80	SHELL OMALA S2 G 1	50			VIVA ENERGY AUSTR	ALIA LTD (1800 651	818/ 13 11 26)		
	No	No	-	-	-	Approved	Yes	-	04-Mar-2020
2335	2335 SHELL SPIRAX S4 CX 10W VIVA E					VIVA ENERGY AUSTRALIA LTD (1800 651 818/ 13 11 26)			
	No	No	-	-	-	None	Yes	-	26-May-2022



(Location Name: Adbri Limited/ CONCRETE & AGGREGATES/ NEW SOUTH WALES/ HY-TEC/ AUSTEN QUARRY, Child Locations

Included)

Stock	Product Name				Supplier (Emergency Contact)				
Number	Hazardous	Dangerous Good	UN number	Packing Group	Hazchem Code	Status	In Stock Inventory	Risk Assessment	SDS Date
2390	ULTRA CLEAR COMPRESSOR 46 GULF WESTERN OIL ((02) 9673 9600/ 13 11 26)								
	No	No	-	-	-	None	Yes	-	31-May-2018
2398	ULTRION 8187				ECOLAB PTY LTD (180	00 205 506, +64 7 95	58 2372)		
	No	No	-	-	-	None	Yes	-	16-Nov-2018
1259	WINDEX GLASS & MO	RE MULTI-SURFACE			S.C. JOHNSON & SON, INC. (+1 866 231 5406)				
	No	No	-	-	-	None	Yes	Available	20-Jun-2019



Adelaide Brightor

ABL-HSE-GSS-07-01

RISK ASSESSMENT TOOL

"Uncontrolled Copy When Printed"

Risk Assessment Guidance

Refer to consequence table in "ABL-HSE-GSS-07-04 HSE Risk Assessment Process". Only Safety examples are provided below.

CONSEQUENCE (the	extent of	the harm or damag	e with current cont	rols in place)								
Negligible	- Minor Injuries requiring First aid Treatment.											
Minor	- Single	- Single or multiple injuries requiring medical treatment.										
Serious	- Single	or multiple injuries	requiring hospitali	sation and incurred	a loss of more than	n one full shift.						
Significant	- Single	severe injury causi	ng irreversible pern	nanent disability or	impairment or sing	le fatality.						
Catastrophic	- Incide	nt with short or long	term effects causi	ng multiple fatalitie	s.							
LIKELIHOOD (the cha	ance of th	e situation occurrin	g with current cont	rols in place)								
Rare Unlikely Possible Probable Very Likely CONSEQUENC	Rare - The consequence may only occur in exceptional circumstances or 'the probability is close to zero'. Unlikely - The consequence is not likely to occur. There is confidence that it will not occur although it is conceivable. Possible - The consequence could occur sometime or 'l've heard of it happening'. Probable - The consequence is likely to occur. It is known to occur, or not surprised as it has happened' several times. Very Likely - It is almost certain that the consequence will occur. Common or frequent occurrence. LIKELIHOOD CONSEQUENCE Rare Unlikely Possible Probable Very Likely											
Negligible		1	2	4	7	11						
Minor	3 5 8 12 16											
Serious	6 9 13 17 20											
Significant	10 14 18 21 23											
Catastrophic		15	19	22	24	25						

	Negligible	Minor	Serious	Significant	Catastrophic
Health & Safety	Minor Injuries requiring First aid Treatment. No ongoing health effects. Near Miss with the potential consequence for the injuries above	Single or multiple injuries requiring medical treatment No ongoing health effects. Near Miss with the potential consequence for the injuries above.	Single or multiple injuries requiring hospitalisation and incurred a loss of more than one full shift. Near Miss with the potential consequence for the injuries above.	Single severe injury causing irreversible permanent disability or impairment or single fatality. Near Miss with the potential consequence for the injuries above.	Incident with short or long term effects causing multiple fatalities. Near Miss with the potential consequence for the injuries above.
Environmental Impact	Minor incident with minimal or no lasting effects. Onsite uncontrolled release immediately contained. Clean-up completed within 12 hours. Less than 5 litre spill	Incident with minor effects on the environment. Onsite uncontrolled release not immediately contained or minor off site release. Clean-up completed within 72 hours. 10 to 20 litre spill.	Incident with medium term effects on the environment. Offsite uncontrolled release with an effect on the environment for one year.	Incident with serious environmental effects. Offsite uncontrolled release not contained causing of up to 10 years impact duration.	Catastrophic incident with impairment of the ecosystem function. Significant and identifiable risk to humans, animals and plant species.
Community	Low level incidentMinor- medium impact issue Public concern with a small local groupPublic concern restricted to one local complaintPotential for local media attentions		Medium impact issue Ongoing public concern with a local group or community Involvement of non-government organisation - Local media	Serious social incident Ongoing local and/or state issue. Involvement of government department/s and non- government organisations. National Media	Very Serious Incident Ongoing state or national issue. Involvement of federal government department/s and non-government organisations. National media
Cost or Damages	< \$10K	\$10K - \$50K	\$50K - \$150K	\$150K - \$1M	> \$1M
Investigation Team	Local Supervisor or Manager OHS representative or member of the OHS committee	Plant Manager Team Leader / Supervisor OHS Representative or Member of the OHS committee	Plant Manager (Investigation leader) HSE Manager Manager external to site OHS Representative or member of the OHS committee	Manager External to site or discipline (Investigation Manager) HSE Manager Site Manager OHS Representative External resources or assistance as required	Manager External to site or discipline (Investigation Manager) HSE Manager Site Manager OHS Representative External resources or assistance as required
Investigation Outcomes	Completion of incident report form including: Brief report covering: Description of incident Contributing factors Prevention Measures	 Completion of incident form: Brief report covering the following: Brief statement from person's involved and witnesses Description of incident Contributing factors Prevention measures 	 Completion of incident form: Investigator Terms of Reference. Incident timeline. Detailed report covering the following: Detailed statement for person's involved and witnesses Description of incident Contributing factors Recommendations and prevention measures 	 Completion of incident form: Investigator Terms of Reference. Incident timeline. Detailed report covering the following: Detailed statement for person's involved and witnesses Description of incident Contributing factors Recommendations and prevention measures 	 Completion of incident form: Investigator Terms of Reference. Incident timeline. Detailed report covering the following: Detailed statement for person's involved and witnesses Description of incident Contributing factors Recommendations and prevention measures



Adelaide Brighton



				"Uncontrol	llod Copy	Nhon Printod"		
				oncontrol	neu copy (when Finited		
HAZARD	SOURCE	HEALTH EFFECTS	INFO	MEASUREMENT	ASSESS RISK	CONTROLS	REVIEW	RESPONSIBLE
Appendix 8G	1	-	1			Environmen	tal Hazard M	anagement Matri
Dust	Traffic	Worker Health Issues; Eye injuries/infections due to airborne dust. Respiratory problems due to inhalation. Skin allergic reactions due to contaminated dust.	Monthly dust monitoring results consistently below the required concentrations. Annual report states effectiveness of SWMP in detaining dust on site.	Worker Health Measurement; Dust survey carried out around plant to determine employee exposure levels. Workers Health examinations conducted. Environmental Measurement; Dams tested for quality of water.	Worker 13 Environ ment 17	Site Soil and Water Management Plan (SWMP) developed for dust management. (Landscape & Rehabilitation Management Plan) Water truck used on a regular basis during operating hours to minimise dust production from haul road traffic. Quarry main access road sealed to minimise dust production. Sprinklers system installed to assist with dust minimisation on roadways. Dust suppression installed on plant equipment to reduce plant produced airborne dust. Dust suppression system continually improved and more effective methods sourced.	Worker 9 Environ ment 13	All
	Plant	Environmental Issues; Downpour of rain washing silt and contaminants into waterways.	Worker exposure and protection provided proved acceptable.	Annual Ecology survey. Monthly and annual water and dust collection samples analysed. Heavy Rain Event Site Inspection.		Work area kept clean and tidy to prevent build-up of dust/debris. Suitable PPE ie respirator or dust mask available and used when & where necessary, employee's trained in the effective use of PPE. Policies in place regarding mandatory use of eye protection i.e. double eye protection when grinding.		

Hy-Tec Industries – Austen Quarry

Status: APPROVED	Owner: HSE Manager	Doc: HTQY-S-HSE-084	Rev: 0.1	Issued: 12 Sep 2012	Page 1 of 12



Adelaide Brighton

HTQY-S-HSE-084

Hy-Tec Industries – Austen Quarry

HAZARD	SOURCE	HEALTH EFFECTS	INFO	MEASUREMENT	ASSESS RISK	S CONTROLS		RESPONSIBLE
	Cleaning	Dust contamination affecting local ecosystem biodiversity. Airborne dust carried off site.				Workers trained in the selection and use off appropriate eye and respiratory protection. Confined space to be cleared of all atmospheric hazards and air quality monitored by competent person before and during confined activities. Ensure sufficient ventilation is available before entry proceeds. (Extraction fans must be used if welding is being carried out)		
	Blasting					 Test results to return readings within allocated concentrations, if pollutant concentrations exceeded, contingency plans implemented. If accidental water discharge occurs emergency response plans ready to contain TSS, involving spill stations and CAR systems in QMS. If wet weather discharge occurs daily water samples to be taken to monitor PH, TSS & Oil & Grease. Continuous sampling apparatus in place for airborne dust monitoring. Blasting carried out by competent external contractors with the minimizing of dust and fly-rock production considered. 		

Status: APPROVED	Owner: HSE Manager	Doc: HTQY-S-HSE-084	Rev: 0.1	Issued: 12 Sep 2012	Page 2 of 12





Hy-Tec Industries – Austen Quarry

HAZARD	SOURCE	HEALTH EFFECTS	INFO	MEASUREMENT	ASSESS RISK	CONTROLS	REVIEW	RESPONSIBLE
Waste Material	Production	Environmental Issues; General waste disposal. Site Waste leaving quarry site into local catchments.	Regulator limits production to 1.1Mt per annum extracted from the premises. Approximately 60,000 tonnes of overburden produced, stockpiled and rehabilitated annually.	Environmental Measures; Production and subsequent waste quantities recorded.	Worker 1 Environ ment 8	Quarry produced overburden is reused in rehabilitation program Daily production monitored and filed in database. Office produced recyclable material is stored in skip bin and periodically collected to be treated off site. Office waste or non-recyclables collected and disposed of off site in an approved manner.	Worker 1 Environ ment 5	LA/RW

		Worker Health	Worker Health Measures;		Sunscreen and drinking water located in crib rooms, plant		
		Issues;		Worker	operation rooms and offices.	Worker	
	Sup		Incident and near miss	13		9	
Heat	Sull	Dehydration.	reports.	Environ	Employees to partake in safe work methods with regard to heat,	Environ	All
				ment	including adequate PPE.	ment	
		Exhaustion.	Worker Health	1		1	
			Examinations		Employees educated on the dangers of heat stress and methods		

Status: APPROVED	Owner: HSE Manager	Doc: HTQY-S-HSE-084	Rev: 0.1	Issued: 12 Sep 2012	Page 3 of 12



Adelaide Brighton

HTQY-S-HSE-084

Hy-Tec Industries – Austen Quarry

HAZARD	SOURCE	HEALTH EFFECTS	INFO	MEASUREMENT	ASSESS RISK	CONTROLS	REVIEW	RESPONSIBLE
		Skin Damage.		Fmplovee		to combat the problem.		
	Plant/Machin ery			Communications – Tool Box Talks, Safety Alerts.		Working in heat and dehydration educational signs displayed in crib rooms.		
						First aid officer on site during working hours.		
						Adequate first aid equipment available. Drinking Water to be supplied to all Visitors, Contractors & Employees.		
	Hot Work					Long sleeves and trousers to be worn during work activities and a hat to be worn when working outdoors.		
						Ensure compliance with work/rest requirements as outlined in ABL-HSE GOS-29-02 Fatigue Management Requirements.		
						Drivers to be instructed in Fatigue Management requirements.		
						Mobile equipment to have functioning air conditioning system installed, when necessary windows tinted to protect drivers from sun exposure.		
	Tools					Screens in place to segregate work area. Hot work signs erected.		
						On site meteorological station to survey daily temperatures.		
						Only competent/trained personnel to carry out hot work.		
						Ensure hot work is conducted in a designated hot work area with a Hot Work Permit/JSA/SWMS to be completed and filed.		

Status: APPROVED	Owner: HSE Manager	Doc: HTQY-S-HSE-084	Rev: 0.1	Issued: 12 Sep 2012	Page 4 of 12		



Adelaide Brighton

HTQY-S-HSE-084

Hy-Tec Industries – Austen Quarry

HAZARD	SOURCE	HEALTH EFFECTS	INFO	MEASUREMENT	ASSESS RISK	CONTROLS	REVIEW	RESPONSIBLE
Noise	Traffic Plant Blasting	Worker Health Issues; Industrial deafness.	Quarry worker level of noise protection deemed effective. Quarry boundary noise below requirements. PPV and air blast overpressure readings below limits.	Worker Health Measurements; Worker Health Examinations. Worker Noise Exposure survey undertaken by external company. Worker noise PPE and knowledge examined to determine adequacy. Quarry boundary monitored to determine level of quarry produced noise. Blast ground vibration peak particle velocity and air blast overpressure monitored at each blast by acting company. Survey undertaken to determine noise levels in proximity to plant machinery.	Worker 21 Environ ment 1	 Hours of work restricted. 5:00-22:00 Monday-Thursday, 05:00-20:00 Friday, 5:00-15:00 Saturday Blasting restricted between 10:00 – 15:00 Monday to Friday. Blast noise monitoring conducted at each blast by external contractors carrying out blasts. Monitoring conducted on air blast overpressure (limit 115dBL) and ground vibration peak particle velocity (limit 5mm/s) at location deemed closest sensitive location not under control of the Quarry, (Hartley Village). Regular maintenance carried out on equipment to minimise noise production. Sound proofing on generators and generator sheds. Sound proofing on mobile plant engine compartments. Instruction on selection and use of suitable hearing protection. Hearing protection worn as required. PPE signage displayed in appropriate locations. Noise exposure level map displayed in crib room depicting noise levels in proximity to plant. Noise limits <35dB(A) for 15minute intervals. 	Worker 14 Environ ment 1	All

Status: APPROVED	Owner: HSE Manager	Doc: HTQY-S-HSE-084	Rev: 0.1	Issued: 12 Sep 2012	Page 5 of 12
		Delle Déleted			





Hy-Tec Industries – Austen Quarry

HAZARD	SOURCE	HEALTH EFFECTS	INFO	MEASUREMENT	ASSESS RISK	CONTROLS	REVIEW	RESPONSIBLE
Hazardous Substances	Chemicals Fuels Waste Oil (plant/machi nery)	Worker Health Issues; Chemical burns. Fume inhalation. Poisoning. Flammable substances. Environmental Issues; Hazardous substances leeching into groundwater/wat erways.	Monthly Coxs River monitoring has remained below required limits.	Worker Health Monitoring; Incident and Near miss reports. Workers health examination conducted. Environmental Measures; Catchments water quality monitoring monthly and annually.	Worker 13 Environ ment 21	 SDS register kept and maintained on site. Suitable storage facilities/bunded area available. Suitable PPE available and used as required. Safer substances sourced and used where possible. Personnel suitably trained/informed in the process of refuelling plant, generators and handling of hazardous substances. Maintenance to be carried out in designated area. Danger signage in place (Corrosive Substance, etc). Procedures in place for major environmental incidents. Spillages cleaned up immediately using spill kits available. All spill kit stocks maintained, correct spill kit procedure form located with each spill kit. <u>Fuel - Large Spill</u> In the case of large spills contact relevant personnel Stop leak without risk. Move containers from spill area. Approach the release from upwind Prevent entry into water courses, basements or confined areas. Wash spillages into an effluent treatment plant or proceed as follows. Contain and collect spillage with non- combustible, absorbent material e.g. sand, earth, vermiculite or diatomaceous earth and place into a container according to local legislation. Determine flammability and if required use spark-proof tools and explosive proof equipment. Dispose of 	Worker 9 Environ ment 14	All

Status: APPROVED	Owner: HSE Manager	Doc: HTQY-S-HSE-084	Rev: 0.1	Issued: 12 Sep 2012	Page 6 of 12
		Data Drivtada			





Hy-Tec Industries – Austen Quarry

"Uncontrolled	Conv	When	Printed"
Uncontrolled	COPY	vvnen	Timteu

HAZARD S	SOURCE	HEALTH EFFECTS	INFO	MEASUREMENT	ASSESS RISK	CONTROLS	REVIEW	RESPONSIBLE
						 9) Contaminated absorbent material may pose the same hazard as the spilt product 10) In the case of spillage on water, prevent the spread of product by the use of suitable barrier equipment. 11) Recover product from the surface 12) Dispose of via an appropriately licensed waste disposal Small Spill 1) Stop leak without risk. 2) Move containers from spill area 3) Absorb with an inert material and place in appropriate waste disposal container. 4) Determine flammability and if required use spark-proof tools and explosion-proof equipment. 5) Dispose of via an appropriately licensed waste disposal Contents of spill kits to be inspected quarterly & restocked after use. Oils and hydraulic fluids to be disposed of in accordance with Environmental legislation. First aid officer on site during working hours. Adequate first aid equipment available. If soil contamination is discovered water management to be constrained by guidelines grapping by the DEC 		

Status: APPROVED	Owner: HSE Manager	Doc: HTQY-S-HSE-084	Rev: 0.1	Issued: 12 Sep 2012	Page 7 of 12



Adelaide Brighton

HTQY-S-HSE-084

Hy-Tec Industries – Austen Quarry

HAZARD	SOURCE	HEALTH EFFECTS	INFO	MEASUREMENT	ASSESS RISK	CONTROLS	REVIEW	RESPONSIBLE
Water	Dams River System	Environmental Issues; Coxs River water contamination. Coxs River Ecology.	Ecology study found no significant changes had occurred to flora and fauna. Microinvertebra tes survey results determined 'not possible to attribute any microinvertebra te changes to quarry activities'. Quarry effects on groundwater levels negligible.	Environmental Measures; Coxs River water samples tested monthly both upstream and downstream. Annual monitoring of Coxs river microinvertebrates. Additional annual testing carried out on quarry catchments. Discharge Requirements. -pH; 6.5-8.5 -Oil/Grease; 10mg/L -Electrical Conductivity; <1500us/cm -Total Suspended Solids; <30 mg/L -Biochemical Oxygen Demand; 20 Heavy Rain Event Site Inspection.	Worker 1 Environ ment 21	 Site Soil and Water Management Plan developed for water management. (Water Management Plan, WMP & Landscape & Rehabilitation Management Plan) Individual catchments analyzed for best fit water management plan, developed for capacity up to a 20 day 95th percentile rain event. Site soil analysis carried out to determine soil characteristics including erodibility. Ground disturbance activities (clearing through to development) scheduled for completion within 6 months. Inspections carried out after heavy rainfall events to examine the soundness of water management systems. Diversion drains constructed around the quarry, diverting clean runoff from upslope catchments around the quarry. In the case of water breach Contingency Plan to be implemented, involving spill stations and CAR system in QMS. All external batters of dams to be grassed with a slope no steeper than 1V:3H. Continual monitoring and maintenance of sedimentation dams. Periodic removal of consolidated sediment from the Quarry 	Worker 1 Environ ment 18	ALL/RW

Status: APPROVED	Owner: HSE Manager	Doc: HTQY-S-HSE-084	Rev: 0.1	Issued: 12 Sep 2012	Page 8 of 12





Hy-Tec Industries – Austen Quarry

HAZARD	SOURCE	HEALTH EFFECTS	INFO	MEASUREMENT	ASSESS RISK	CONTROLS	REVIEW	RESPONSIBLE
	Rainfall					Access Road sediment basins. Water management systems will employ regular maintenance to ensure effectiveness. Including regular inspections and cleaning of under road storm water pipes. Runoff from all disturbance areas is directed to silt dams and sedimentation dams. Water levels monitored and pumped from sediment dams to storage dams to ensure sufficient capacity in the event of significant rain event. Sediment dam water tested and treated prior to discharge at licensed discharge points, to ensure released water meets EPA requirements		
	Groundwater					Samples to be taken and tested daily during discharge events. Annual Report submitted to Council with a summary of water monitoring results, as well as diversion drain and quarry water management condition. Macroinvertebrates monitored upstream and downstream of quarry activities. Sediment dams regularly emptied to maintain required capacity for 5 day 95 th percentile rain event (44mm of rain in any consecutive 5 day period). Prior to ground disturbance activities upslope diversion banks and downstream sediment retention implemented.		

Status: APPROVED	Owner: HSE Manager	Doc: HTQY-S-HSE-084	Rev: 0.1	Issued: 12 Sep 2012	Page 9 of 12
		Data Printada			



Adelaide Brighton

HTQY-S-HS	E-084	Hy-Tec Industries – Austen Quarry							
	"Uncontrolled Copy When Printed"								
HAZARD	SOURCE	HEALTH EFFECTS	INFO	MEASUREMENT	ASSESS RISK	CONTROLS	REVIEW RESPC	NSIBLE	

	Plant/Mobile Plant.					Ensure hot work is conducted in a designated hot work area and Hot Work Permit/JSA/SWMS to be completed and filed. Only competent/trained personnel to carry out hot work. Screens in place to segregate work area.		
Fire	Bushfires.	Worker Health Issues; Burns to employees. Smoke inhalation	Worker Health Measurement; Incident and Near Miss reports. Environmental Measures; WCC fire department fire hazard monitoring.	Worker Health Measurement; Incident and Near Miss reports.	Worker	Equipment to be in good condition and suitable for the task. Electrical equipment must be tested and tagged in accordance with AS3760. Fire fighting equipment fitted to all mobile plant.	Worker 15 Environ	All
	Electrical Fires.	Environmental Issues; Flora and Fauna destruction. Bushfire.		ment 22	Employees trained in first attack fire fighting. Use of flame retardant material to cover susceptible equipment. Adequate fire extinguishers located throughout site. Use of correct PPE for the task/job.	ment 22	Fire Wardens; RW;CM;KK	
	Power Tools				Periodic testing of Fire extinguishers is conducted by an external service provider. First aid officer on site during working hours.			

Status: APPROVED	Owner: HSE Manager	Doc: HTQY-S-HSE-084	Rev: 0.1	Issued: 12 Sep 2012	Page 10 of 12





Hy-Tec Industries – Austen Quarry

HAZARD	SOURCE	HEALTH EFFECTS	INFO	MEASUREMENT	ASSESS RISK	CONTROLS	REVIEW	RESPONSIBLE
	Hot Work					Fire warden present on site during work hours. Adequate first aid equipment available. Bush fire emergency procedure in place.		

Status: APPROVED	Owner: HSE Manager	Doc: HTQY-S-HSE-084	Rev: 0.1	Issued: 12 Sep 2012	Page 11 of 12





Hy-Tec Industries – Austen Quarry

HAZARD	SOURCE	HEALTH EFFECTS	INFO	MEASUREMENT	ASSESS RISK	CONTROLS	REVIEW	RESPONSIBLE
Biodiversity Destruction	Land clearance Ecosystem Contaminatio n	Environmental Issues; Loss of local flora and fauna.	Annual ecology survey has discovered an increase in wildlife diversity within the local catchment.	Environmental Measures; Annual 3 day ecology survey carried out by external company. Monitoring of Aquatic Microinvertebrates.	Worker 1 Environ ment 23	 Vegetation Management Plan in place with both immediate and long term plans. Local native plant seeds collected and raised in nursery to be reintroduced into previously cleared areas. All bund wall areas are rehabilitated with native flora. Long term objectives include post quarry life plans to ensure after life quarry footprint is minimal. Overburden pile continually rehabilitated in accordance with pile growth. Weed control plans in place to monitor weed development and when required sprays used to remove weeds. Flora and Fauna surveys conducted across all parts of quarry lease area. Flora and Fauna species catalogued annually to determine biodiversity fluctuation. Any threatened species identified and plans put in place for protection. 	Worker 1 Environ ment 18	RW/CM

Status: APPROVED	Owner: HSE Manager	Doc: HTQY-S-HSE-084	Rev: 0.1	Issued: 12 Sep 2012	Page 12 of 12





Adelaide Brighton Etd	AFFENDIA													
	Austen Quarry - Risk Register This contents of this risk assessment will be reviewed when new risk identified, procedural review and/or risk / controls not adequate Rick Scra with carteria (Residual Risk)													
			This conte	nts of this	s risk asse	essment will be	reviewed when new risk identified, procedural review a	and/or risk / cont	rols not adequa	ite				
	Risk Identification		Risk Score Witho	ut Controls (Inh	erent Risk)		Control		Risk Score with	Controls (Reside	ual Risk)	Further Action Required		
		Causes (Mihat can cause the	Consequence		Inhoront Rick	Principal Hazard (if		Highest Control Level	Consequence		Poridual Pick	Action Required to achieve Desired Peridual Pick (to be managed in		
Work Activity	Risk relating to activity	hazard to occur)	Principal Hazard)	Likelihood	Score	Management Plan	Control Description	Controls)	Principal Hazard)	Likelihood	Score	Cintillate)		
Electrical - Component Lifecycle Management	>Electrical equipment develop risk which can caused hazard to workers.	> Electrical components can fail due to the amount of use and age.	Catastrophic (Principal Hazard)	Possible	22	Electrical Engineering Control Plan	 > Electrical component to be replaced as per OEM, Australian Standards or Mine Design Guidelines recommendations. > Schedule for replacement to be managed via gearbox. > Repaired or replaced as per safety alerts or information from industry or regulator. 	Engineering / Redesign	Significant	Rare	10			
Electrical - Contractor Management	> Competence of contractors completing work at quarry.	> Electrical work / engineering work is outsourced to a contractor(s).	Catastrophic (Principal Hazard)	Possible	22	Electrical Engineering Control Plan	All plant and equipment to be designed and maintained to the appropriate Australian standards. All electrical contractors are to have applicable trade certificates or appropriate engineering documentation. Electrical tradesperson is nominated to NSW regulator. > All contractors must have appropriate insurances managed by site pass. > Quarry Manager to shall check and maintian a records for the competency of all	Engineering / Redesign	Significant	Unlikely	14			
Electrical - Equipment to test electrical equipment	Electric shock from using electrical test equipment.	> Failure of equipment. > Incorrect equipment used. > Exposed live electrical points.	Significant	Possible	18	Electrical Engineering Control Plan	 All electrical test equipment must be designed for testing the level of voltage anticipated. > Voltage tester must not expose workers to the risk of electric shock. > Test leads and testing devices should be provided with over current protection. > Be free from damage and cracks in insulation. > Also electrical testing screw drivers are not permitted. 	Isolation	Serious	Unlikely	9			
Electrical - General Electrical Risks	> Electric shock / electrocution to workers.	> Workers touching electrical components they do not understand. > Poor or dangerous wiring.	Catastrophic (Principal Hazard)	Possible	22	Electrical Engineering Control Plan	 Only trained and competent workers are to touch electrical components, people approved to work on electrical components must be authorised by the Quarry Manager, > Isolation points to great physical breaks in power to complete tasks, lock out tagged out. Inspection and testing of electrical equipment. Inspections and testing completed on electrical components. Electrical components shall be fitted with residual current devices. Drawing of electrical systems. Electrical asystems within protected areas (washdown areas) will be minimum IP55, electrical asystems within are outside shall be a minimum of IP56. All other work areas should be accessed. 	Engineering / Redesign	Significant	Rare	10			
Electrical - High Voltage	Electrocution	> High voltage	Catastrophic (Principal	Possible	22	Electrical Engineering	> Site does not have high voltage electrical.	Elimination	Negligible	Rare	1			
work	> Electrical equipment develop	> Electrical components can fail	Hazard)	1 OSSIBIC		Control Plan	Decider maintenance shall be completed encuring	Isolation	HeBiBibic	nure	-			
electrical - Maintenance	risk which can caused hazard to workers.	due to the amount of use and age.	Catastrophic (Principal Hazard)	Possible	22	Control Plan	Areguan manuferiance stant be compreted ensuing. > Operation of electrical installation and not impaired by interference, damage or wear. > Live parts are insulated and workers are protected from inadvertent contact. > Earth leakage systems operates effectively. > Not exceeding operating limits. > The installation does not have the potential to start a fire. > Safety integrity limits (SI) are maintained.	ISOIAUUT	Significant	Rare	10			
Electrical - New electrica installations to site.	> New plant / structures can bring new hazards to site.	> Unknown / unforeseen risks / processes	Catastrophic (Principal Hazard)	Possible	22	Electrical Engineering Control Plan	> All new electrical components brought onto the quarry to have design risk review completed, prior to construction. > All new electrical systems brought onto site to have commissioning plan develop and tested for continuity of earth, insulation resistance, polarity, correct circuit connections, earth fault-loop impedance and REO operation. > All new electrical components to have an management of change completed, reviewee by either the OEM or qualified engineer. > A operational risk assessment (pre start up safety review) to be completed on all new electrical components to look for new introduced risks. > All new electrical components to be designed and builta s per Australian standards.	Engineering / Redesign	Significant	Rare	10			
Electrical - Portable powered tools	Electric shock from using tool	 Poorly maintained tool. Tool being used beyond its capacity. 	Significant	Possible	18	Electrical Engineering Control Plan	 > Use battery powered tools as oppose to electrical tools. > All electrical tools must be tagged and tested and inspected by a competent person. > Electric power tools must be inspected piror to use. > All electrical tools must have an RCD fitted for use. 	Substitution	Serious	Unlikely	9			
Electrical - Power Distribution	Electrocution from powerlines	> In ground powerlines > Over head powerlines	Significant	Possible	18	Electrical Engineering Control Plan	Auster quarry has no overhead powerlines. Clearance work permit to be completed if working near overhead power lines or excavating near powerlines on site of any department of the second se	Elimination	Significant	Rare	10			
Electrical - Restoration of Power	f Electrocution from restoration of power	> Daily starting of generator	Significant	Possible	18	Electrical Engineering Control Plan	> Prestart inspection to be completed prior to starting generator for the day. > Procedure and training for starting of generator. > Generated started with out people working within vicinity.	Engineering / Redesign	Serious	Unlikely	9			
Electrical - Restoration of Power	F Electrocution from restoration of power	> Overload trip > Short Circuit trip	Catastrophic (Principal Hazard)	Possible	22	Electrical Engineering Control Plan	 > Reset of power to be completed by an electrician after, fault is identified and repaired. > further tests also carried out to determine it is safe to start-up. > Started with out people working within vicinity. 	Engineering / Redesign	Serious	Unlikely	9			
Electrical - Restoration of Power	Electrocution from restoration of power	> Circuit breaker reset > Blown fuse	Significant	Possible	18	Electrical Engineering Control Plan	> Reset only complete if the fault is known, if fault is unknow then electrician shall complete reset. > If trip occurs second time electrician shall investigate trip. > Lock Out / Tao Dut shall he used for realargement of fuses	Engineering / Redesign	Serious	Unlikely	9			
Electrical - Switchboards and Distribution Boards	> Worker entering switchboard or distribution board in which they are not permitted to access.	> Workers are unaware they are not to access board.	Catastrophic (Principal Hazard)	Possible	22	Electrical Engineering Control Plan	> All boards must be locked preventing worker access. > Only authorised persons are to able to access boards. > Access to cables behind boards are only permitted when competent and with a dearance to work permit. Stimpane in Jucce In Jucce In Educational Installations and access is calificiant.	Isolation	Significant	Rare	10			

Electrical - Switchboards and Distribution Boards	Fire on switchboard / distribution board.	> Dust and heat causing over heating of distribution boards.	Significant	Possible	18	Electrical Engineering Control Plan	 > Boards are contained in sealed room free from dust and contaminates. > Power distribution rooms are also air condition. > Multiple exit points from power distribution rooms, and easy to get away from boards. > No combustible material stored in distribution rooms > Signage indicating controls. 	Engineering / Redesign	Minor	Unlikely	5	
Electrical - Work on live	Electrocution	> Live electrical work	Catastrophic (Principal	Possible	22	Electrical Engineering	> ABL employees and contractor are not permitted to work on live circuits.	Elimination	Negligible	Rare	1	
Explosives - Air quality / contaminates post blast	> Workers / community exposed to dangerous levels of airborne contaminates.	> Wind speed / direction. > Poor blast design.	Catastrophic (Principal Hazard)	Possible	22	Explosives Control Plan	 Controls as per risk (Air Quality & Dust - Workers exposed to dust working onsite (Crystaline Silica)). Onsite monitors to determine is blast dust is exiting site. Exclusion zones for workers. Notification to public and workers on blasting days. Slasting to be postponed is weather conditions not suitable. 	Isolation	Catastrophic (Principal Hazard)	Rare	15	
Explosives - Airblast Overpressure & Ground Vibration.	> Overpressure & Ground Vibration causing injuries to workers / community	> Poor design and plan for blast	Catastrophic (Principal Hazard)	Possible	22	Explosives Control Plan	Philipse insertion and an interested affection of the set of	Engineering / Redesign	Catastrophic (Principal Hazard)	Rare	15	
Explosives - Generation of fly rock	> Fly rock causing injuries to workers / community	> Drill hole stem lengths incorrect, generating face burst and fly rock.	Catastrophic (Principal Hazard)	Possible	22	Explosives Control Plan	 > Shot firer to plan blast hole depth during planning phase. > Exclusion zones to be in place for when blast occurs, including safety margin for expected fly rock distances. > Notification to public (neighbours 48 hours prior) and workers on blasting days. > Post blast review to verify hole depths and exclusion zones are sufficient, for fly rock. 	Engineering / Redesign	Catastrophic (Principal Hazard)	Rare	15	
Explosives - Misfire during blasting.	> Injury to worker, worker being too close to misfire shot.	> Unfired blast holes, Unfired detonator and/or Unfired product, identified post blast	Catastrophic (Principal Hazard)	Possible	22	Explosives Control Plan	> Exclusion zone established when if unfired explosive found. > Shot firer shall manage the misfire, and potentially attempt to refire the shot. > If the shot can not be refired it shall be extracted with a vacuum truck and diluted with water.	Isolation	Catastrophic (Principal Hazard)	Rare	15	
Explosives - Misfire during blasting.	> Injury to worker, worker being too close to misfire shot.	> Unfired detonator / explosive found during excavation.	Catastrophic (Principal Hazard)	Possible	22	Explosives Control Plan	 Exclusion zone established when if unfired explosive found. Competent shot firer to return to site to manage un detonated explosive. 	Isolation	Catastrophic (Principal Hazard)	Rare	15	
Explosives - Preparing for blast.	> Injuries to workers and/or local community. > Damaged to culturally significant sites and other community infrastructure.	> Poor design of blast. > Blasting outside of licenced / approved times.	Catastrophic (Principal Hazard)	Possible	22	Explosives Control Plan	 > Blasts are designed for each specific location, developed by quarry manager in consultation with the shot firer. >> Blast design shall include, drilling plan, blast hole size / load and address other hazards and misfres. >> Shot firing is out sourced to a competent company, contracts and shot firers companies are managed through site pass. >> Shot first / company shall provide safe systems of work for Hy-Tec review. >> Buffers to be established for indigenous heritage / culturally significant sites. >> All blasting must comply with site licences and restrictions. 	Engineering / Redesign	Catastrophic (Principal Hazard)	Rare	15	
Explosives - Storage of explosives	> Detonation / theft of explosives	> Blast cancelled, unplanned event keeping explosives on site.	Catastrophic (Principal Hazard)	Possible	22	Explosives Control Plan	> Explosives are not to be stored on site, shot firer contractors shall only bring explosives onsite when they are needed. > In an unforesen event requires the explosives to be stored on site the Shot Firer must work with the site to develop a plan, ensuring they are compliant with the Explosives Act 2003 and ensemble. In the standards	Isolation	Catastrophic (Principal Hazard)	Rare	15	
Fire - External fire event potentially affecting the site.	Workers being stuck onsite due to fire risk. > Fire fighting agencies accessing site being unaware of risk. > Workers on site to protect assets.	Fire event onsite due to offsite fire event (bush fire).	Catastrophic (Principal Hazard)	Possible	22	Fire Prevention and Protection Management Plan	 Simigraphy management plan for external fire event. Simigraphy rations to be onsite for minimum 5 days (including food and water). The site shall develop a fire plan for the specific fire event, ensuring water carts etc. have water to extinguisher soft fires. Site shall have tools in place for external communication during a fire event and utilise government websites to manage approaching fire and weather conditions. Sites shall expressions for some sleeping. Sites need to manage rad closures and enable workers to leave prior to roads being closed if possible. Open areas need to be available to get to separate people from the fire risk. 	Isolation	Catastrophic (Principal Hazard)	Rare	15	
Fire - External fire event potentially affecting the site.	> Fire to assets / people.	Fire event onsite due to offsite fire event (bush fire).	Catastrophic (Principal Hazard)	Possible	22	Fire Prevention and Protection Management Plan	> Site shall have emergency management plan developed. > Fire management plan shall be available and visible within site. > Maps in place of the site. > Engage with fire authority, to show site and discuss fire plans, prior to incident.	Isolation	Catastrophic (Principal Hazard)	Rare	15	
Fire - Hot Work	Fire as a result of hot work outside of workshop.	> Unknown hazards due to hot work.	Catastrophic (Principal Hazard)	Unlikely	19	Fire Prevention and Protection Management Plan	> All hot work outside of the workshop must be completed with a hot work permit. > Fire extinguishers must be in place for hot work, as well as wetting areas when outside with combustible material. > Hot works are not permitted outside during total fire bans.	Administrative	Catastrophic (Principal Hazard)	Rare	15	
Fire - Management of fire equipment	Failure of fire equipment when needed.	> Poorly maintained or incorrect fire equipment.	Catastrophic (Principal Hazard)	Possible	22	Fire Prevention and Protection Management Plan	> All fire equipment must be inspected as per OEM recommendations or Australian Standards. > Workers must be trained in fire equipment. > Suitable volume and type of fire equipment must be in place for each different	Engineering / Redesign	Serious	Possible	13	
Fire - Plant / Mobile Plant	Fire while people are in or operating mobile plant.	> Malfunction within machine.	Catastrophic (Principal Hazard)	Rare	15	Fire Prevention and Protection Management Plan	 Machines are inspect preshift for any signs of potential faults. All machines on site are inspected and maintained as per OEM recommendations. Machines are fitted with fire extinguishers enabling workers to escape machinery. Machines are easy to escape from or have multiple evacuation methods. 	Engineering / Redesign	Serious	Rare	6	

Fire - Pressurised gas cylinders	Pressurised gas cylinders failing causing risk.	 > Fire spreading to cylinder storage. > Failure of gas cylinder causing flammable risk. > Storage of non compatible material. 	Significant	Possible	18	Fire Prevention and Protection Management Plan	> All cylinders must be stored upright, and chained, in designated storage area. > All cylinders must be inspected to ensure they are free from damage and complaint to Australian standards. > Cylinders are exchanged through supplier, ensuring they are complaint. > SOF must be consulted with to ensure non compatibilitie items are not stored together. > All gas cylinders shall be isolated from areas, by either one-hour firewall or by minimum of three metre distance.	Isolation	Serious	Possible	13	
Fire - Refuelling of vehicles	Vehicle catching fire due to being on during refuelling.	> Vehicle being on during refuelling. > Ignition sources within refuelling area.	Catastrophic (Principal Hazard)	Unlikely	19	Fire Prevention and Protection Management Plan	All refuelling to occur in designated refuelling areas. All vehicles refuelled onsite are disel not unleaded petrol. Closed systems for refuelling, minimal oxygen within fuelling areas. Vehicles must be turned of during refuelling, unless completed under specific risk assessment. No ignition sources are permitted within refuelling areas. Price oxtinguisters / fire protection systems. Daily pre start inspections on vehicles.	Engineering / Redesign	Significant	Rare	10	
Fire - Spontaneous Combustion	> Site has no risk of spontaneous combustion		Negligible	Rare	1	Principal Hazard However Not Present	> Nil no risk present	Elimination	Negligible	Rare	1	
Fire - Storage Oils / flammables	Fire of oils / flammable liquids	> Fire spreading to oil / flammable storage.	Catastrophic (Principal Hazard)	Unlikely	19	on Site Fire Prevention and Protection Management Plan	 > All flammable material must be stored in flammable storage cabinets. > All chemicals must be labelled. > All chemicals shall be stored in suitable lidded containers. > SDS must be consulted to not store incompatible material together. 	Isolation	Significant	Rare	10	
Fire - Waste oils / flammables	Fire of waste oils / flammable liquids	> Poor housekeeping of flammable equipment leading to fire or making fire worse.	Significant	Unlikely	14	Fire Prevention and Protection Management Plan	Elementals material and be tread user treat interm better protect All rags must be disposed of correctly, and work areas cleaned at the end of the job. All waste oil must be stored in designed oil storage containers. Suitable fire extinguishers within areas to manage flammability risk. Large volumes of flammable material not stored on site.	Administrative	Significant	Rare	10	
Fire - Welders / cutters	Welding / cutting of material.	> Fire / explosion of welding equipment.	Significant	Unlikely	14	Fire Prevention and Protection Management Plan	 > Regular inspections of all welding and cutting units. > All cables and leads must be kept free from grease and oil. > Flash back arrestors must be fitted to all welders / cutters. > Welding screens must be in place to prevent injuries to other workers. > All people welding must wear the correct PPE. 	Engineering / Redesign	Serious	Unlikely	9	
Fixed Plant & Structures Boot (Bin)	Worker falling into the bin.	 > Workers needs to access bin area or unintentional access of bin area. > Haul truck / Loader falling into bin 	Significant	Possible	18	Not Applicable	 > Pedestrians to not access boot unless under Clearance to work permit. > Haul Truck Drivers are not to leave cabin when parked at the boot. > Tyre bump stop in place to prevent truck falling into the bin (Boot) 	Engineering / Redesign	Significant	Rare	10	> Signed to be installed indicating no pedestrian access.
Fixed Plant & Structures Boot (Bin)	Rocks spilling out of the bin, causing injury to worker below the bin.	> The bin can be over full, > Larger load of rock to go into bin.	Significant	Possible	18	Mechanical Engineerin Control Plan	 Boot (bin) has edge spillage boards which are 1800mm higher than the boot. > Every 5 years a mechanical engineer completes inspections of all plant and structures for signs of fraigue. > Workers are not to be within 6 metres of the bottom of the boot when loads are being tupped into the bin. > Haul truck sizes are designed in accordance with volume of material the boot can handle. 	Isolation	Significant	Rare	10	 Tool toos talk and signage to be in place explaining no go area for base of boot. Register to be developed of what is to be inspected every 5 years.
Fixed Plant & Structures	Entanglement of operator within conveyor.	> Worker can access conveyor with potential to get entangled.	Significant	Possible	18	Not Applicable	All conveyor are guarded to prevent access. Work on conveyors to be done under a Clearance to work permit and lock out, tag out process. JOTO in place to prevent unplaned plant movements. JOROWEY Site of Ende to the access prototo to conveyor start. Conveyor starts finded to the access prototo to conveyor start.	Engineering / Redesign	Serious	Unlikely	9	
Fixed Plant & Structures	Fires within bearing / rollers	> No grease within bearing causing friction fire to start.	Serious	Unlikely	9	Mechanical Engineerin Control Plan	Veekly inspection of whole tertiary, inspecting all elements. Daily visual inspection of plant prior to start up. Bearing temperature inspection Weekly shudown maintenance Fire extinguishers on plant.	Administrative	Serious	Rare	6	
Fixed Plant & Structures	Debris falling from conveyor, impacting worker.	 > Overloading conveyors. > People accessing conveyor at incorrect place. 	Serious	Possible	13	Mechanical Engineerin Control Plan	Largest size rock around 350mm with minimum potential fall height. Workers do not need to access between boot and tertiary crusher, post tertiary crush maximum rock size is 20mm. > Workers wear hard hats when outside walking around site. > Workers to only pass under conveyor system under designated walkways. > Skirt rubbers at transfer points, skirt rubbers centralise rocks onto centre of the conveyor.	Substitution	Minor	Rare	3	> Enclose conveyor under designated walkways.
Fixed Plant & Structures Conveyors	Failure of plant structures.	> Heavy corrosion of plant caused by dust and elements.	Catastrophic (Principal Hazard)	Unlikely	19	Mechanical Engineering Control Plan	Every S years a mechanical engineer completes inspections of all plant and structures for signs of fatigue. Weekly inspection of whole tertiary, inspecting all elements. Daily visual inspection of whole nant nine to start in	Engineering / Redesign	Catastrophic (Principal Hazard)	Rare	15	
Fixed Plant & Structures Conveyors	Cuts and lacerations from conveyor belts.	> Conveyors can have sharp edges.	Minor	Probable	12	Not Applicable	> Workers generally do not need to handle conveyor belts. > Worker wear category 3 cut resistant gloves.	PPE	Negligible	Unlikely	2	
Fixed Plant & Structures	Falling into the crusher.	> Maintenance activities / inspections of crusher.	Significant	Possible	18	Mechanical Engineering Control Plan	1 > Guarding in place to prevent people failing into crusher, > Guarding inspected daily during prestart to ensure all guarding is in place. > Any other work bar inspection / top up oil requires clearance to work permit and working at heights permit.	Isolation	Significant	Rare	10	
Crushers	maintenance.	inspections of crusher.	Significant	Unlikely	14	Control Plan	- Solver and the solver in the solver to be completed where worker means to access crusher Any other work bar inspection / top up oil requires clearance to work permit and working at halable normit	Solution	Minor	Rare	3	
Fixed Plant & Structures	Entanglement within crusher drive components.	> Maintenance activities / inspections of crusher.	Significant	Unlikely	14	Mechanical Engineering Control Plan	- Guarding in place to prevent people falling into crusher, - Guarding inspected daily during prestart to ensure all guarding is in place Guarding in place to ensure limb in unable to access moving parts Any other work bar inspection / top up oil requires clearance to work permit and working at height permit.	Isolation	Significant	Rare	10	
Fixed Plant & Structures Crushers	High pressure injections from hydraulic systems	> Failure of hoses and seals.	Significant	Unlikely	14	Mechanical Engineering Control Plan	s > All high pressure hydraulic components that propose a potential risk have burst protection in place or guarding. > lock Out Tae Out for all worker working on hydraulic systems	Engineering / Redesign	Serious	Rare	6	> Develop dear doctor letter for a HPI injury and emergency response plan.

Fixed Plant & Structures -> Limb pinch between moving	> Maintenance activities /				Mechanical Engineering	> Guarding in place to prevent people falling into crusher.	Isolation				
Crushers parts of machine.	inspections of screens.	Serious	Unlikely	9	Control Plan	 Guarding in practice of percent people to many end of the source all guarding is in place. Guarding in place to ensure limb in unable to access moving parts. Any other work bar inspection / top up oil requires clearance to work permit and working at behavior. 		Minor	Rare	3	
Fixed Plant & Structures Crushers & Screens Fall into crusher or screen resulting in injury or fatality	Removing blockages from crushers and screens	Significant	Possible	18	Mechanical Engineering Control Plan	 > Hand rails and suitable guarding in place to prevent accidental fall into danger areas > Warning signs in place to inform of inherent dangers. > 2 persons working in the area at all times 	Engineering / Redesign	Significant	Rare	10	
Fixed Plant & Structures - Incident within confined space Crushers & Screens	Parts of the crusher are confined spaces for workers.	Significant	Possible	18	Not Applicable	 Only registered and qualified persons are allowed to conduct work in confined spaces in accordance with AS2865 - Safe work in a confined space. A clearance to work and confined space permit must be used when entering confined space. A clearance to work and confined space permit must be used when entering confined space. A clearance to work and confined space activities, adequate ventilation must be present prior to entry. Ensure sufficient ventilation is available before entry proceeds. [Extraction fans must 	Administrative	Significant	Unlikely	14	
Fixed Plant & Structures -> Pinch between moving parts machine. > Limb crush points	of > Maintenance activities / inspections of screens.	Serious	Unlikely	9	Mechanical Engineering Control Plan	> Guarding in place to prevent people falling into screen, > Guarding in place to prevent people falling into screen, > Guarding in place to ensure limb in unable to access moving parts. > Any other work, bar inspection / greasing requires clearance to work permit and working to bitwise anomaly.	Isolation	Minor	Rare	3	
Fixed Plant & Structures - Entanglement within screens. Screens	> Maintenance activities / inspections of screens.	Serious	Unlikely	9	Mechanical Engineering Control Plan	 > Guarding in place to prevent people falling into screen, > Guarding inspected daily during prestart to ensure all guarding is in place. >> Guarding in place to ensure limb in unable to access moving parts. > Any other work, bar inspection / greasing requires clearance to work permit and 	Isolation	Minor	Rare	3	
Fixed Plant & Structures - Engulfment within screens, dur Screens maintenance.	ing > Maintenance activities / inspections of screens.	Significant	Unlikely	14	Mechanical Engineering Control Plan	> Lock Out, Tag Out for all worker to be completed where worker needs to access screens. > Any other work, bar inspection / greasing requires clearance to work permit and working at heights permit	Isolation	Minor	Rare	3	
Fixed Plant & Structures - Fall from heights - Parts of plan Tertiary crushing plant are elevated with the potential for workers to fall from heights	 t > Completing pre start inspections and greasing moving parts. > Slips while on plant, due to wet surfaces 	Significant	Possible	18	Mechanical Engineering Control Plan	 All plant is guarded to prevent workers fall from height, handrails. Only workers with operational need access tertiany crusher platforms. Any other work, bar inspection / greasing requires clearance to work permit and working at heights permit. Workers war lace up safety footwear. 	Engineering / Redesign	Significant	Rare	10	
Ground & Strata > Bench may fail causing injurie Management - Bench to workers below or workers or Failure the bench.	 S > Bench may fail due to weathered material. > Pooling of water or rain event washing away material. > Undercut of highwall. 	l Catastrophic (Principal Hazard)	Possible	22	Ground Control Management Plan	Moriers shall not be within the too of the highwall, highwalls which have poor strata shall exclusion zones as determined by an engineer. Seotechnical studies undertaken of benches. Daily visual inspection looking for evidence of ground stability or strata failure. Drilling and operations completed as per pit design. Catch benches in place.	Engineering / Redesign	Catastrophic (Principal Hazard)	Unlikely	19	
Ground & Strata > Dumping over water or over a Management - Dumping highwall.	 > Movement of dump. > Incorrect position of vehicle to dump. > Debris from dumping not cleared. 	Catastrophic (Principal Hazard)	Possible	22	Ground Control Management Plan	> Floor shall be slopping upwards. > The Quarry Manager or Supervisor shall determine safe distance from the tip edge, a minimum of 5 metres from windrow to be used. > The dozer shall remain on the dump at all time while tipping is occurring. > Should the dump / tip edge show signs of cracking, tipping shall stop and the face be reinspected.	Engineering / Redesign	Catastrophic (Principal Hazard)	Unlikely	19	
Ground & Strata Management - Fill areas / Overburden	Poor compaction of fill areas. Water ingress into fill areas water ingress into fill areas causing wash away. > Design failures / maintenance of dump areas. > Seismic event.	Catastrophic (Principal Hazard)	Possible	22	Ground Control Management Plan	Filled areas shall be designed and compacted as per geotechnical report. Daily inspections of working areas. Water pressure & corrosint to be considered for design of fill areas. Sumps to be in place. Post a seismic activity, fills areas shall be inspected for possible failure. Posta seismic activity, fills areas shall be inspected for possible failure. Posta or fill areas should be no higher than 20 metres unless advised received from geotechnical advice. Persons shall not access the toe of a dump on foot unless an inspection has been completed prior for lose material / rocks. Should dump areas be unsafe, geotechnical advice sort and access prohibited until remedial work has taken place. For any abnormal events a risk assessment must be completed to develop a plan to	Engineering / Redesign	Catastrophic (Principal Hazard)	Unlikely	19	
Ground & Strata > Failure of highwall (Wedge / Management - Highwall Slop failure).	 > Incorrect slop angle, too steep. > Loose material on highwall. > Excessive highwall face height. > Undercut of Highwall. 	Catastrophic (Principal Hazard)	Possible	22	Ground Control Management Plan	 Decrease slop angle shall be consider whilst undertaking geotechnical slope design. Workers shall not be within the toe of the highwall, highwalls which have poor strata shall exclusion zones as determined by an engineer. Daily visual inspection looking for evidence of ground stability or strata failure. 	Engineering / Redesign	Catastrophic (Principal Hazard)	Unlikely	19	
Ground & Strata Management - Highwall injuries to workers below or Failure due to water.	Water pooling behind highwall. Large weather event washing away parts of highwall. Incorrect slop design (Too Steep). Incorrect bench design (Too Narrow). Ground water within pit. Undercut of Highwall.	Catastrophic (Principal Hazard)	Possible	22	Ground Control Management Plan	 Decrease dog angle shall be consider whilst undertaking geotechnical doge design. Workers shall not be within the toe of the highwall, highwalls which have poor strata shall exclusion zones as determined by an engineer. Daily visual inspection looking for evidence of ground stability or strata failure. Regular performance monitoring to be undertaken of highwalls. Face height shall not exceed the Geotechnical report requirements. Geotechnical Engineer shall be engaged as required to reassess mining methodology. Faces of highwall to not exceed 15 metres, or higher than the loader / excavator can reach for the purposes of scaling. 	Engineering / Redesign	Catastrophic (Principal Hazard)	Unlikely	19	
Ground & Strata > Highwall may fail causing Management - Highwall injuries to workers below or Failure workers on top of the highwall.	> Seismic activity	Catastrophic (Principal Hazard)	Possible	22	Ground Control Management Plan	 > Decrease slop angle shall be consider whilst undertaking geotechnical slope design. > Workers shall not be within the toe of the highwall, highwalls which have poor strata shall exclusion zones as determined by an engineer. > Post a seismic activity, highwall shall be inspected for possible failure, daily inspections. > Face height shall not exceed the Geotechnical report requirements. > Blasting shall also be completed in accordance with the explosives control plan. 	Engineering / Redesign	Catastrophic (Principal Hazard)	Unlikely	19	

Constant of Charles	· For shore of the bound date to	Black and the second sector starts	1			Coursed Courteral	 Plan to destance d. Conditionation and the second states are set to all one. 	Frankright (Badaster				,
Ground & Strata Management - Highwall Failure	> Fracture of Highwall due to Blast.	> Blast onsite weakening strata and causing potential failure onsite.	Catastrophic (Principal Hazard)	Unlikely	19	Ground Control Management Plan	 > site is designed, for blasting activities to take place. > Comply with explosives control plan. > Post blast inspection conducted > Bunding built to canture loose rocks which could fall from highwall 	Engineering / Redesign	Catastrophic (Principal Hazard)	Rare	15	
Ground & Strata Management - Water	> Water may corrode / damage structure within the pit.	> Water pooling behind highwalls and road surfaces.				Ground Control Management Plan	 Scaling control capture toose toose writed too a support of the provided of the p	Engineering / Redesign				
Management		> Large weather event washing away parts of highwall. > Ground water within pit.	Catastrophic (Principal Hazard)	Possible	22		toe or crest of critical slops. > Decrease slop angle shall be consider whilst undertaking geotechnical slope design. > Daily visual inspection looking for evidence of ground stability or strata failure. > Regular performance monitoring to be undertaken of highwalls. > Face height shall not exceed the Geotechnical report requirements. > Geotechnical Engineer shall be engaged as required to reassess mining methodology.		Catastrophic (Principal Hazard)	Unlikely	19	
Ground & Strata Management - Working near base of highwall	> Highwall may fail causing injuries to workers below highwall face.	> Failure of highwall	Catastrophic (Principal Hazard)	Possible	22	Ground Control Management Plan	> Decrease slop angle shall be consider whilst undertaking geotechnical slope design, and faces shall not exceed the geotechnical requirements. > Workers shall not be within the too of the highwall, highwalls which have poor strata shall exclusion zones as determined by an engineer. > Catch benches shall be in place. > People and vehicles shall not be with 15 metres of the too of a highwall unless they have accessful to the data.	Engineering / Redesign	Catastrophic (Principal Hazard)	Unlikely	19	
Health Effects - Biological Health	> Health effects due to virus.	> Unknown sources. > Water contaimination.	Catastrophic (Principal Hazard)	Possible	22	Health Control Plan	 Follow recommendation from state and federal governments and world health organisation. Piskis assess any health pandemics. Pistike water for drinking and town water purchased for hand washing etc. Densee wither world heaven the sense to assess to use the sense. 	Isolation	Catastrophic (Principal Hazard)	Rare	15	
Health Effects - Psychosocial Hazards	> Physiological hazards for workers.	> Work / Job Stress > Non work related factors	Significant	Possible	18	Health Control Plan	 Employee assistance program available for workers and promoted. > Workers have access to support through different levels of management. > Revider reviews with workers on performance and expectations 	Administrative	Significant	Rare	10	
Health Effects Air Quality & Dust - Asbectos	> Inhalation of asbestos within workplace	 > Asbestos in Buildings. > Asbestos naturally occurring. 	Catastrophic (Principal Hazard)	Possible	22	Health Control Plan	> No Asbestos onsite.	Elimination	Negligible	Rare	1	
Health Effects Air Quality & Dust - Community exposed to dust working onsite.	> Dust onsite due to mining operations, effecting community health.	 Mining a product with a high silica content. Breaking rock to make dust and little rocks. 	Catastrophic (Principal Hazard)	Unlikely	19	Health Control Plan	> Dust monitors on perimeters to monitor if dust is leaving site. > Silica content of product known (product has high silica content). > Local Community is a significant distance from mine. > Water used within processes to reduce airborne dust (Watercart / stockpile sprays / productions).	Isolation	Significant	Rare	10	
Health Effects Air Quality & Dust - Dust generated on roads from vehicles (Crystaline Silica).	> Workers inhaling silica dust when moving around the site.	> Vehicles on roads generating dust.	Catastrophic (Principal Hazard)	Possible	22	Health Control Plan	 > People shall not walk around quarry for general access, people shall be transported by vehicle to parts of the quarry. > All vehicles access the quarry shall have windows up at all times. > All vehicles accessing quarries shall have air conditioning, with air set to recycle. > Water cart / spinkler system available to wet roads. > All vehicles shall have door seals which are regularly inspected and replaced as per OEM recommendations. 	Isolation	Serious	Unlikely	9	
Health Effects Air Quality & Dust - Dust in Workshop (Crystaline Silica).	 > Dust and mud build up in workshop, exposure to workers when needs to be cleaned. > Dust in service area. 	 > Workers need to sweep up dust and mud in workshop. > Dust settles on equipment. > Dirt floor within service area. 	Catastrophic (Principal Hazard)	Possible	22	Health Control Plan	 > Mud guards on vehicles, particularly articulated vehicles. > Vehicles are wash down prior to entering workshop. > Some dust does enter workshop, however is washed out to minimise exposure. 	Administrative	Minor	Unlikely	5	
Health Effects Air Quality & Dust - Fume exposures	> Health effects due to fume exposure.	 > Chemicals onsite. > Mobile plant / vehicles. 	Significant	Unlikely	14	Health Control Plan	> All chemicals onsite are known and SDS is reviewed, dangerous inhalation risk chemicals are not required on site. > Chemicals are stored in well ventilated areas. > Vehicles constructurid in will wantilated areas.	Engineering / Redesign	Serious	Rare	6	
Health Effects Air Quality & Dust - Human movement generating dust (Crystaline Silica).	 > Workers inhaling silica dust when within vehicle cabin. > Dust within offices / lunchrooms, continuing worker exposure during break times. 	> Areas where people enter / exit vehicles or offices having product build up.	Catastrophic (Principal Hazard)	Possible	22	Health Control Plan	 Vehicles are not to be swept out, however vacuumed out and wiped down with a damp cloth. Rooms have doors seals. Rooms have air-conditioning which are regularly serviced. 	Administrative	Serious	Unlikely	9	
Health Effects Air Quality & Dust - Workers exposed to dust working onsite (Crystalline Silica).	> Dust onsite due to mining operations, effecting workers health.	 Mining a product with a high silica content. Sreaking rock to make dust and little rocks. Wind. 	Catastrophic (Principal Hazard)	Possible	22	Health Control Plan	Ste completes annual dust exposure monitoring of work groups (SEGs). (frequency of testing may vary due to exposure). Silica content of product known (product has high silica content). Workers complete 5 yearly health Survellance for silica exposure health effects. (frequency of sverillance may vary due to exposure). Water used within processes to reduce airborne dust (Watercart / stockpile sprays / sprinkler systems). All vehicles onsite shall have an enclosed cabin, with air condition and adequate door seals. Pagular / Inspections maintenance to take place on all equipment seals and filtration systems (DEM recommendations). Operations to stop if the dust can not be controlled on windy days. Workers walking around site have respirators available.	Isolation	Significant	Unlikely	14	
Health Effects Air Quality & Dust - Workers exposed to dust working onsite (Crystalline Silica).	> Dust onsite due to mining operations, effecting workers health.	> Operating vehicle / mobile plant. > Excavating. > Grading. > Loading. > Tipping.	Catastrophic (Principal Hazard)	Possible	22	Health Control Plan	Water used within processes to reduce airborne dust (Watercart / stockpile sprays / sprinker systems). All vehicles onsite shall have an enclosed cabin, with air condition and adequate door seals. All vehicles onsite shall have an enclosed cabin, with air condition and adequate door seals. Aegular / inspections maintenance to take place on all equipment seals and filtration systems (DEM recommendations). OEM maintains vehicle where applicable, OEM also completes cabin leak detection testing. Windows on vehicles must be closed at all times. Cabins to be cleaned regulary, wiped with wet cloths and vacuumed.	Isolation	Significant	Unlikely	14	

Health Effects Air Quality & Dust - Workers exposed to dust working onsite (Crystalline Silica).	> Dust onsite due to mining operations, effecting workers health.	> Drilling for shot.	Catastrophic (Principal Hazard)	Possible	22	Health Control Plan	 > Drill rig must have a fully operational dust collector. > Drill bench is prepped prior to drilling. > Drill of sphalt have an enclosed cabin, with air condition and adequate door seals. > Windows on vehicles must be closed at all times. > Cabins to be cleaned regularly, wiped with wet cloths and vacuumed. > Vehicle doors must be ifelt closed when out of the vehicle. > Completed cabin leak detection testing. > No mauthorised to bench whils drilling operations in place. 	Isolation	Significant	Unlikely	14	
Health Effects Air Quality & Dust - Workers exposed to dust working onsite (Crystalline Silica).	> Dust onsite due to mining operations, effecting workers health.	> Blasting	Catastrophic (Principal Hazard)	Possible	22	Health Control Plan	 Access is restricted to blast area. Slasting will not take place if weather conditions are not acceptable. Blast management plan in place and all people suitable distance from blast and airborne dust / fume. Post blast examination to not take place until the dust has settled. 	Isolation	Significant	Unlikely	14	
Health Effects Air Quality & Dust - Workers exposed to dust working onsite (Crystalline Silica).	 Dust onsite due to mining operations, effecting workers health. 	> Crushing operations. > Conveyor transport.	Catastrophic (Principal Hazard)	Possible	22	Health Control Plan	Wetting product prior to and during the crushing process. Water sprays on conveyors. Signed restricted access to crushing plant. Signed restricted access to crushing plant. Site completes annual dust exposure monitoring of work groups (SEGs). (frequency of testing may vary due to exposure). Workers complete 5 yearly health Surveillance for silica exposure health effects. (frequency of swellance may vary due to exposure). In plant design minimise drop distances between product transfer points. Operations to stop if the dust can not be controlled on windy days or frost. Workers walking around site have respirators available.	Isolation	Significant	Unlikely	14	> Complete static dust monitoring to determine high risk areas around crushing plant. > Look to separate people from crushing plant, utilise cameras. > Skirts / coverage on transfer points.
Health Effects Air Quality & Dust - Workers exposed to dust working onsite (Crystalline Silica).	> Dust onsite due to mining operations, effecting workers health.	> Working from primary crusher control room.	Catastrophic (Principal Hazard)	Possible	22	Health Control Plan	 Control room is not near primary crusher. Control room has air conditioner which is set to recuriculte and is serviced monthly. Site completes annual dust exposure monitoring of work groups (SEGs). (frequency of testing may vary due to exposure). 	Isolation	Minor	Rare	3	
Health Effects Air Quality & Dust - Workers exposed to dust working onsite (Crystalline Silica).	> Dust onsite due to mining operations, effecting workers health.	> Working from tertiary crusher control room.	Catastrophic (Principal Hazard)	Possible	22	Health Control Plan	Wetting product prior to and during the crushing process. Water sprays on conveyors. Water sprays on conveyors. Water sprays on conveyors. Crusher has enclosed cabin, with air condition and adequate door seals, air conditioner to be serviced every month. Site completes annual dust exposure monitoring of work groups (SEGs). (frequency of testing may vary due to exposure). Workers complete 5 yearly health Surveillance for silica exposure health effects. (frequency of surveillance may vary due to exposure). In plant design minimise drop distances between product transfer points. Operations to stop if the dust can not be controlled on wind ydays or frost. Workers omlaing around site have respirators available.	Isolation	Significant	Unlikely	14	 Complete static dust monitoring to determine high risk areas around consing plant. Look to separate people from crushing plant, utilize cameras. Consider moving control room away from crushing plant.
Health Effects Air Quality & Dust - Workers exposed to dust working onsite (Crystalline Silica).	> Dust onsite due to mining operations, effecting workers health.	> Crushing plant maintenance and cleaning.	Catastrophic (Principal Hazard)	Possible	22	Health Control Plan	Wash/wet screens and structures, prior to maintenance. > Extended grease lines in place from restricted space. > Use of small mobile equipment to access under conveyors and structures. > Use of sposable coveralls and dust respirators (and trained) when completing maintenance on dusty areas. > Clothing can be washed onsite. > Workers are trained in silica and exposure risks and trained in correct use / fitment of	Engineering / Redesign	Significant	Unlikely	14	
Health Effects Air Quality & Dust -Confined Space	> Build up of fume / oxygen depleting substance.	> Machine in operation near confined space. > Chemical / substance releasing fume.	Significant	Unlikely	14	Not Applicable	All confined spaces must be identified and have signage warning of prohibited access. The atmosphere of the confined space must be tested prior to entry, ensuring there is sufficient oxygem within the space. Continual air monitoring must occur in the confined space. Confined spaces entry shall only occur under a permit and risk assessment. A stand by person must be in place for a confined space entry. Both the stand by and confined space entrant must be trained in confined space.	Engineering / Redesign	Serious	Rare	6	
Health Effects Air Quality & Dust -Workers exposed to dust working onsite (Crystalline Silica).	> Dust onsite due to mining operations, effecting workers health.	> Washing operations. > Conveyor transport. > Movement of vehicles around site. > Wind.	Catastrophic (Principal Hazard)	Possible	22	Health Control Plan	 > Site completes 3 yearly dust exposure monitoring of work groups (SEGs). (frequency of testing may vary due to exposure). > Site is a wet process, and does not generate dust through dredge and washing operation (furthermore, product is not crushed down so does not normally form a fine powder). > The site has its own weather station, which enables the site to monitor conditions where dust could generate. This enables the site to water cart operation in risk areas. > Workers are trained in silica and exposure risks. 	Isolation	Significant	Unlikely	14	> Workers complete 5 yearly health Surveillance for silica exposure health effects. (frequency of surveillance may vary due to exposure).
Health Effects on Body - Diesel powered vehicles and machinery.	> Inhalation of diesel particulate.	> Diesel powered vehicles can generate diesel particulate.	Catastrophic (Principal Hazard)	Possible	22	Health Control Plan	Vehicles operate in open spaces and all vehicles operate with windows up, with air conditioning. Vehicles are also fitted with particulate filters. Vehicles are used to work in dises frame. Disest powered machinery maintained as per OEM recommendations. Oracle advised to be sound force are used as for data subjects and	Isolation	Minor	Rare	3	
Health Effects on Body - Ergonomics	> Musculoskeletal disorders	 Poorly designed equipment. Hazardous manual handling. 	Serious	Possible	13	Health Control Plan	 > All equipment designed with ergonomic consideration. > All new machinery is risk assessed through our Change Management process. > Routine tasks have operating procedures and risk assessments in place. > Permit system in place for non vortuine task. > Hazardous Manual Handling Standard - ABL-HSE-GOS-12. 	Engineering / Redesign	Serious	Unlikely	9	
Health Effects on Body - Fitness for work	> Fitness for work (fatigue)	 Insufficient time to recover between shifts. Poor shift start and finish times. 	Catastrophic (Principal Hazard)	Unlikely	19	Health Control Plan	> All personnel shall comply with ABL-HSE-GOS-29-02 Fatigue Management. > A site specific fatigue risk assessment shall be undertaken if an employee works more than 60 hours in a week.	Administrative	Catastrophic (Principal Hazard)	Rare	15	
Health Effects on Body - Fitness for work	> Fitness for work (drugs / alcohol)	> Worker under the effects of drugs and/or alcohol.	Catastrophic (Principal Hazard)	Unlikely	19	Health Control Plan	 > Workers shall tell their supervisor if they are on any prescription medication. > Random drug and alcohol testing of workers. > Workers shall have zero alcohol in their system. 	Administrative	Catastrophic (Principal Hazard)	Rare	15	

Health Effects on Body -	> Unknown health effects from	> Exposures to hazardous				Health Control Plan	> Register onsite of all hazardous substances.	Engineering / Redesign				
Hazardous Substances	being exposed to hazardous substances.	substances.	Catastrophic (Principal Hazard)	Possible	22		 Region of nances our mice and accessible, SDS register is reviewed annual. SDS kept onsite and accessible, SDS register is reviewed ensuring any additional controls re implemented. Attempt to replace dangerous chemicals with low risk chemicals. 	engineering / neuengin	Serious	Unlikely	9	
							Signage in place for any specific chemical hazards. All flammable goods stored in suitable storage locations.					
Health Effects on Body - Hot Weather / High Humidity	> Heat stress / heat stroke.	> Hot weather / humidity.	Serious	Possible	13	Health Control Plan	 Mobile plant fitted with air conditioners, and all office spaces / building fitted with air conditioners. Potential to increase breaks if needed or postpone work with no protection from heat. Workers able to carry water with them, in vehicles / on job. Workers have long pants, shifts, hat and sunscreen to protect them from UV. 	Elimination	Minor	Unlikely	5	
Health Effects on Body - Noise	> Industrial hearing loss.	> Continual noise over 85dBA	Serious	Possible	13	Health Control Plan	Workers operate within vehicle cabins, vehicle cabins are designed to be under exposure standard. Bury quite, buying machinery which when in cabin operates at low decibels. Vorkers isolated from noisy equipment and breaks taken away from noisy areas. Noise survey mapping completed on a 5 yearly taks. Your any taken and the mine site. Signs indicating areas where excessive noise may be and where hearing protection is needed. Machinery maintained to minimise noise.	Administrative	Serious	Unlikely	9	
Health Effects on Body - Vibration	> Effects on body due to vibration	> Vibration while operating mobile plant.	Serious	Possible	13	Health Control Plan	 > Workers operate within vehicle cabins, vehicle cabins and seats are designed to reduce / eliminated vibration exposure. > Maintenance on mobile plant as per OEM recommendations. 	Engineering / Redesign	Minor	Unlikely	5	
Health Effects on Body - Welding	> UV burns. > Health effects from fume.	> Welding light and fume.	Significant	Unlikely	14	Not Applicable	> Incident - Instant remoting professes. > Welders use correct PPF such as welding helmets and leather apron and gloves. > Sume extraction equipment. > Designated Hot work area.	Engineering / Redesign	Minor	Possible	8	
Inundation / Inrush - Gas	> Site is an open cut quarry and there is no risk of gas in workings.		Negligible	Rare	1	Inundation and Inrush Management Plan	> Nil no risk present	Elimination	Negligible	Rare	1	
Inundation / Inrush - Water offsite.	> Water from quarry affecting local community.	> Man made dams and rivers / lakes over flowing or giving way impacting local community.	Significant	Rare	10	Inundation and Inrush Management Plan	> Site is away from local community and possible flood risk from quarry. > Quarry is designed to only capture the water they are licenced to hold, in excessive rain event water will run oft quarry in controlled manner. > Pumps able to move quarry water offsite in controlled manner. > Inspections and management of water within and leaving quarry. > Diversion systems in place such as, overflow channels, direct water away from	Engineering / Redesign	Serious	Rare	6	
Inundation / Inrush - Water onsite.	> Water into workings putting worker at risk of drowning.	> Quarry water washing through site.	Significant	Rare	10	Inundation and Inrush Management Plan	 > Water drains from product very slowly. > Pipelines and drains in place to divert the incoming water into the quarry sumps. > Sumps built to capture and store water. > Water can be pump around site to manage water. 	Engineering / Redesign	Serious	Rare	6	
Inundation / Inrush - Water onsite.	> Water into workings putting worker at risk of drowning.	> Man made dams and rivers / lakes above workings giving away, washing through site.	Significant	Rare	10	Inundation and Inrush Management Plan	 Sites designed with all dams at low points on the site, water washing through site is limited to what pumps can push up hill. Roads and areas where water pools is inspected post rain event and during daily inspections. Diversion systems in place such as, overflow channels, direct water away from workings and structure of dams. Pegular inspections of dams and dam walls. 	Isolation	Serious	Rare	6	
Inundation / Inrush - Water onsite.	> Water into workings putting worker at risk of drowning.	> Ground water rising into workings.	Serious	Unlikely	9	Inundation and Inrush Management Plan	Flow of ground water into working is very slow. Sinspection of quarry each day to ensure no excessive water. Sumps in olare to move water out of working areas.	Engineering / Redesign	Minor	Unlikely	5	
Inundation / Inrush - Water onsite.	> Water into workings putting worker at risk of drowning.	> Significant rain event	Significant	Rare	10	Inundation and Inrush Management Plan	 Site work to stop in excessive rain events, as roads and visibility could be un safe. Sites designed with all dams at low points on the site, water washing through site. Roads and areas where water pools is inspected post rain event and during daily inspections. Diversion systems in place such as, overflow channels, direct water away from workings and structure of dams. 	Engineering / Redesign	Serious	Rare	6	
Mine Shaft & Winding	> No risk onsite.	> No risk onsite.	Negligible	Rare	1	Not Applicable	> No risk onsite.	Elimination	Negligible	Rare	1	
Outburst - Gas	> Site is an open cut quarry and there is no risk of gas in workings.		Negligible	Rare	1	Principal Hazard However Not Present on Site	> Nil no risk present	Elimination	Negligible	Rare	1	
Plant & Structures - Maintenance of plant	> Unable to complete safe maintenance / servicing on equipment.	> Safety devices not fitted to plant.	Catastrophic (Principal Hazard)	Possible	22	Mechanical Engineering Control Plan	 All plant on sire must be rick assessed ensure safety devices and warning signals are in place and in suitable positions. > Inspections in place to ensure safety devices are in working order, apart of pre start up inspection. > Servicing completed on safety and warning systems. > Lock out/ Tag Out process, to verify isolation points re effective. > Clearance to work permit to be completed for non standard maintenance tasks. > Upon completion of maintenance work, all plant to returned to operational design. 	Engineering / Redesign	Catastrophic (Principal Hazard)	Unlikely	19	
Plant & Structures - Maintenance of plant	> Injuries to person	> Release of energy	Significant	Possible	18	Not Applicable	 > All plant to be designed to enable isolation of energy sources. > Lock Out / Tag Out and Clearance to work process. 	Isolation	Significant	Rare	10	
Plant & Structures - Boom Lift (Boom Length Greater than 11m)	> Person fall from boom lift	> Failure of boom lift	Catastrophic (Principal Hazard)	Possible	22	Mechanical Engineering Control Plan	 Anarimer's resentative maintenance and inspections. People using boom lift must she the applicable high risk work licence. Boom lift nust she fitted with crusher bar. Boom lift capacity must not be exceeded. People working within basket must be attached to basket with lanyard. Boom lift used must be sittable for all terrain. Scruting and the bin lanks for sonels nationative with home lift. 	Engineering / Redesign	Significant	Unlikely	14	

Plant & Structures - Contractor Management	 Competence of contractors completing work at quarry. Advising risky solutions 	> Mechanical engineering work is outsourced to a contractor(s).	Catastrophic (Principal Hazard)	Possible	22	Mechanical Engineering > Mechanical engineer to complete 5 yearly inspection of all fixed plant and structures. Engineering / Redesi Control Plan > All plant and equipment to be designed and maintained to the appropriate Australian standards. > All plant and equipment to be designed and maintained to the appropriate Australian standards. > All mechanical contractors are to have applicable trade certificates or demonstrate minimum of 2 years working within industry. completing that style of task. > All contractors must have appropriate insurances managed by site pass. > Quarry Manager to shall check and maintain a records for the competency of all contractors who complete maintenance works.	n Significant	Unlikely	14	
Plant & Structures - Hirer Plant & Equipment	on site.	processes	Catastrophic (Principal Hazard)	Possible	22	Avia new plant prought onto the quary to be risk assessed prior to use. Implicit plant brought onto the quary to be risk assessed prior to use. Implicit plant brought onto site, to used under clearance to work permit and any other applicable permits. > Hile equipment suppliers to be of suitable ABL standard to provide equipment to ABL sites. > Procurement processes to establish suitable suppliers as well as sub contractor	Significant	Unlikely	14	
Plant & Structures - Inspections / Maintenance of plant	> Plant develop risk which can caused hazard to workers.	> Plant and structures can deteriorate over time and operation.	Catastrophic (Principal Hazard)	Possible	22	Mechanical Engineering All plant is to be maintained as per OEM specifications, Australian Standards, Mine Design Guidelines and information from relevant safety alerts. Engineering / Redest Design Guidelines and information from relevant safety alerts. Engineering / Redest Design Guidelines and information from relevant safety alerts. File cycle of plant to also be establish as per OEM recommendations, and maintenance completed by qualified person(s). All plant has a daily visual inspection, per start-up inspection. All plant has a daily visual inspection, per start-up inspection points have indivial inter numbers. Bit Monthly quary inspections completed. Bit Monthly quary inspections completed. Bit Monthly quary inspections completed. Bit Monthly quary inspections denoting any susse, corrective action is developed and entered into Gearbox for completion. Fit inspections denoting any susse, corrective action is developed and entered into Gearbox for completion. Bit inspection is encipient.	n Significant	Unlikely	14	
Plant & Structures - Ladders & Scaffolding	> Worker fall from ladder.	> Failure of ladder enabling worker to fall.	Significant	Possible	18	Mechanical Engineering All ladders shall have a formal 3 monthly inspection completed. Engineering / Redesi 2-All portable ladders shall Australian standards and be of industrial quality, capacity Engineering / Redesi 150kg or greater. > All scaffolding shall be completed by a scaffolding company who has qualified scaffolders.	n Significant	Unlikely	14	
Plant & Structures - Lifting with cranes.	> Fall of load.	> failure of lifting equipment	Catastrophic (Principal Hazard)	Unlikely	19	Mechanical Engineering > No person to stand or be under suspended load. Isolation Control Plan > All crant lifts must have a lift plan with clarance to work or procedure for lift. > Cranes must be compliance with Australian standard. > All crant ge quipment must be inspected every three months. > Qualified dogman to sling appropriate loads.	Serious	Unlikely	9	
Plant & Structures - New plant to site / Modification to plant	> New plant / structures can bring new hazards to site.	> Unknown / unforeseen risks / processes	Catastrophic (Principal Hazard)	Possible	22	Mechanical Engineering > All new plant throught onto the quarry to have design risk review completed, prior to construction. Engineering / Redesi Self Lew plant > All new plant brought onto site to have commissioning plan develop and executed to look for possible risk. > All new plant to have an management of change completed, reviewed by either the OEM or qualified engineer. > A operational risk assessment (pre start up safety review) to be completed on all new plant to look for new introduced risk.	n Significant	Unlikely	14	
Plant & Structures - Non Destructive Testing	> Plant develop risk which can caused hazard to workers.	> Parts of plant can fail due to the amount of use	Catastrophic (Principal Hazard)	Possible	22	Machanical Engineering > Non destructive testing to be completed on equipment as per OEM, Australian Engineering / Redesi Control Plan Standards or Mine Design Guidelines recommendations. Schedule for Non destructive testing to be managed via gearbox. > All non destructive testing to be completed by a NATA certified testing facility. > If non destructive testing to be completed by a NATA certified testing facility. > If non destructive testing to sc to prohibitive, item is to be replaced prior to item being out side of service life. > If non destructive testing is cost prohibitive.	n Significant	Unlikely	14	
Plant & Structures - Pressure vessels	> Pressure vessel failure causing explosion.	 > Not maintained or inspected. > Collision with pressure vessel. 	Catastrophic (Principal Hazard)	Possible	22	Mechanical Engineering > All pressure vessel must be inspected annual, by an external qualified provider. Isolation Control Plan > Pressure vessels must comply with Australian Standards. > All pressure vessels must be protected from collision with mobile plant. > All pressure vessels must be protected in a secured place. > Pressure vessels flatted with pressure relief valves.	Serious	Rare	6	
Plant & Structures - Vehicles with rubber tyres.	> Failure of Rim or tyres.	> Poor maintenance of rim or tyre enabling failure.	Significant	Possible	18	Mechanical Engineering > All rims to complete non destructive testing (10000 hours on new or 5000 hours on pre tested) as per OEM / Australian Standards. Engineering / Redesi > Person who completes work on rims / tyres must be competent in rim management, with competence managed in site pass and preferable work for the OEM. > Daily inspections completed on wheel assemblies and tyres. > Tyres are inspected to ensure inflation is correct as per OEM requirements, tyres shall be tested with a pressure gauge. > Tores and the pressure gauge.	Significant	Unlikely	14	
Plant & Structures - Vehicles with rubber tures	> Failure of Rim or tyres.	> Rubber tyre vehicles which have come into contact with electricity or heating.	Catastrophic (Principal Hazard)	Unlikely	19	Mechanical Engineering > Any rubber tyred vehicle which has come into contact with high voltage electricity or Control Plan besing shall be isolated in a 300m exclusion zone for a minimum of 24 hours.	Serious	Rare	6	
Road - Bodies of Water	> Vehicle enter body of water.	> Unaware of body of water.	Catastrophic (Principal Hazard)	Possible	22	Koads and Uther >> bunding shall be erected within 5 metres of the sloping edge, not the waters edge. Isolation Vehicle Operative Scale > Signed in place warning of locations of bodies of water. Isolation Management Plan > Life Buoy located around bodies of water. Signed Scale Sca	Serious	Rare	6	

Road - Design of roads within quarry	> Collision of vehicles.	> Poor roads / conditions enabling vehicle collision.				Roads and Other Vehicle Operating Areas	> All two-way travel roads should be 3 times the width of the widest vehicle, if not possible road must include radio call point and vehicle passine points.	Engineering / Redesign				
			Catastrophic (Principal Hazard)	Possible	22	Management Plan	 Jedaily two way roads would have a centre berm to separate vehicles. No road shall be parrover than 1.5 times the width of the widest vehicle which will travel laong it. All berms shall be half the wheel height of the biggest vehicle site. Roads shall be made of suitable material and maintained so they are in a safe condition. Roads shall be made of suitable material and maintained so they are in a safe scondition. Sonds shall be the signed with cross-fails of no greater than 5 degrees. > Drainage provision shall be installed on all roadways and benches to removed pooled water. > Where possible centre berms shall be used as a road divider. > Intersections, Crest and blind corrers should be eliminated, if they can not be eliminated then a specific risk assessment from have vehicle traffic. 		Significant	Unlikely	14	
Road - Interaction with Power Lines	> Vehicle collision with overhead powerlines	 > Unknown vehicle height. > Unknown powerline height. 	Catastrophic (Principal Hazard)	Possible	22	Roads and Other Vehicle Operating Areas Management Plan	> No overhead powerlines on site.	Engineering / Redesign	Significant	Rare	10	
Road - Maintenance of Roads	> Unplanned movement of vehicle travelling on roads, causing collision.	> Road condition deteriorates due to poor maintenance.	Catastrophic (Principal Hazard)	Possible	22	Roads and Other Vehicle Operating Areas Management Plan	 > Road ways must be regularly maintained and watered. > All workers must be notified at pre-start or toolbox talk, if roads are in poor condition or being maintained during shift. > Obtat dea she detris shall be removed from road ways. > Road ways shall be inspected for cracking, sinking or slippages during / after any monod or bhowsing. 	Engineering / Redesign	Serious	Unlikely	9	
Road - Refuelling Stations	> Vehicle collides with re fuelling station	> Unplanned movement of vehicle, roll away.	Significant	Possible	18	Roads and Other Vehicle Operating Areas Management Plan	>Fixed refuelling stations shall be listed on a sites traffic management plan. > Refuelling stations must be designed and constructed as per AS1940. > Physical barriers must be in place to prevent collision with refuelling stations.	Isolation	Serious	Unlikely	9	
Road - Traffic Management	 > Unplanned movement of vehicle travelling on roads, causing collision. 	> Vehicle operators not aware of road rules.	Catastrophic (Principal Hazard)	Possible	22	Roads and Other Vehicle Operating Areas Management Plan	 All vehicles have two way radios to call operators who may be not following road rules. All people are inducted to site and trained in traffic management rules. Plus annual refresher training of drivers. Signage onsite directing vehicles, and signage is compliant to AS1744:1975. Signage is in visible location where they do not generate a hazard and they are place far enough away from a hazard to enable an operator to stop. Site traffic management maps. 	Engineering / Redesign	Significant	Unlikely	14	> Site shall complete specific site walk through risk assessment for traffic management, identifying heights of berms, one / two way roads, placement of signage, speed limits, radio call points, parking areas, and dealing with road hazards (Crests, blind corners, Intersections), pedestrian integration.
Road Vehicle Operations - Access and Egress of all Mobile Plant.	> Fall while accessing or exiting mobile plant.	 > Design of access / egress. > Damage to access / egress. 	Serious	Possible	13	Not Applicable	> Three points of contact for accessing mobile plant. > Fall protection in place for mobile plant. > Review each piece of plant for access and egress, prior to introduction to site. > Mobile plant operators have appropriate PPE. > Pre-Start inspection on all mobile plant.	Engineering / Redesign	Serious	Rare	6	
Road Vehicle Operations - Collision with fixed plant	> Collision with fixed plant	> Machinery needs to access areas near fixed plant to tip / load.	Significant	Possible	18	Roads and Other Vehicle Operating Areas Management Plan	> Speed limits within congested 15km/h. > Signage reinforcing all site speed limits. > Reversing cameras in place.	Administrative	Serious	Possible	13	
Road Vehicle Operations - Congested Work Areas	> Collision of vehicles within congested work zones Heavy Vehicle V Heavy Vehicle	> Certain work areas (Boot, Loader, Stockpile area, loading zones) have multiple vehicle movements.	Catastrophic (Principal Hazard)	Possible	22	Roads and Other Vehicle Operating Areas Management Plan	Speed limits within congested 15km/h. Fadio communication between vehicles Signape reinforcing all site speed limits. Seversing cameras in place. Flashing lights for dust / dawn operations. Designated stop and hold points, and exclusion zones.	Isolation	Serious	Possible	13	
Road Vehicle Operations - Congested Work Areas	> Collision of vehicles within congested work zones Heavy Vehicle v Light Vehicle	> Certain work areas (Boot, Loader, Stockpile area, loading zones) have multiple vehicle movements.	Catastrophic (Principal Hazard)	Possible	22	Roads and Other Vehicle Operating Areas Management Plan	 Speed limits within congested 15km/h. Radio communication between vehicles, light vehicles must give way to all heavy vehicles. Signage reinforcing all site speed limits. Sleager reinforcing all site speed limits. Flashing lights and whip flags on light vehicles. 	Isolation	Serious	Possible	13	
Road Vehicle Operations - Fire on mobile plant.	> Fire on mobile plant.	> Failure on mobile plant causing fire.	Significant	Possible	18	Fire Prevention and Protection Management Plan	 > Fire fighting equipment in place to enable driver to escape from vehicle, and of suitable size for self escape. > Fire extinguishers tested every 6 months. > Workers trained in fire equipment. > Yre start inspection on machinery and equipment maintained as per OEM recommendition 	Engineering / Redesign	Significant	Rare	10	
Road Vehicle Operations - General Vehicle Movements	> Collision of vehicles.	 > Unknown vehicle movement, > Unable to see other vehicle. > Vehicle causing more severe injury to occupants. 	Catastrophic (Principal Hazard)	Possible	22	Roads and Other Vehicle Operating Areas Management Plan	> All vehicles must be fitted two-way radios, > All vehicles must have a flashing light, > Head lights, indicator lights and brake lights. > Vehicles (4.5 frome must be fitted with hvip flags. > All mobile glant must be fitted with revening beepers and a fire extinguisher. > All off highway vehicles, must meet road worthy inspections for NSW. > All off highway vehicles must comply with maintenance as prescribed where possible DEM. > Roads designed to protect workers and minimise integration between heavy and light vehicles. > Workers are trained and competent to drive vehicle. > Collision avoidance technology, vehicle reversing alarms regularly tested. > Pre-Start checklist completed.	Engineering / Redesign	Significant	Unlikely	14	
Road Vehicle Operations - General Vehicle Movements	> Collision with building / Structure.	> Building in position where run away vehicle can have collision.	Catastrophic (Principal Hazard)	Unlikely	19	Roads and Other Vehicle Operating Areas Management Plan	 Speed calming devices installed. Sarricating and Bolizet to slow/stop vehicles. Separation between vehicles and pedestrian areas. Run off areas for vehicles. On site speed millimits based on road and operating condition. Road is maintained to prevent it being slippery. 	Engineering / Redesign	Serious	Rare	6	

Road Vehicle Operation: - General Vehicle Movements	s > Collision with person.	> Unknown vehicle movement, > Unable to see other person	Significant	Possible	18	Roads and Other > Designated walk ways for pedestrians, pedestrians not to walk around moving heavy Isolation Vehice Operating Areas > Pedestrians wear high visibility clothing. > All public plant must be fitted with reversing beepers. > All mobile plant must be fitted with reversing beepers. > All off highway vehicles must comply with maintenance as when possible as per OEM. > Collision avoidance system for site visitors. > Collision
Road Vehicle Operations - General Vehicle Movements	 S Collison with other Vehicle, structure or pedestrian. 	 > Driver not fir for work (fatigue or drugs / alcohol. > Distracted mobile phone (personal device). 	Catastrophic (Principal Hazard)	Possible	22	Roads and Other > No mobile phones use while operating vehicles A-5 TGVM. Advers are permitted to use mobile phones when driving on a Vehicle Operating Meras > No workles: A-5 TGVM Werkers are permitted to use mobile phones when driving on a Management Plan > Drivers trained in fatigue management and have regular breaks. > All persons onsite must be free from the effects of drugs or alcohol. Adverse of the second s
Road Vehicle Operations - Loading box trailers for light vehicles (<4.5T	s > Failure of trailer.	 > Overload vehicle > Bucket damages vehicle 	Significant	Possible	18	Not Applicable > Light vehicle box trailer to not be loaded on site. Elimination Negligible Rare 1
Road Vehicle Operations - Loading of tipper trailers.	s > Failure of tipper vehicle.	> Overloading of truck / trailer.	Minor	Possible	8	Not Applicable > Maximum capacity of tippers are known. > Scales on loader to indicate weight of load. > loader driver qualified and evenly distributes load. > All tipper vehicles are site inspected.
Road Vehicle Operations - Operating vehicle in poor visibility conditions	s > Collison with other Vehicle, structure or pedestrian.	> Night, > Smoke, > Fog.	Catastrophic (Principal Hazard)	Possible	22	Roads and Other > Vehicles are fitted with head lights and tail lights. Vehicle Operating Areas > All vehicle have flashing lights. Vehicle operating Areas > All vehicle have flashing lights. Management Plan > Cheatrast of drive to the conditions Catastrophic (Principal Hazard)
Road Vehicle Operation: - Roll over / Fall Over	s > Vehicle roll over or fall over	> Poor road condition, > Load shift, > Too fast in corner,	Catastrophic (Principal Hazard)	Probable	24	Mechanical Engineering > Further information in Roads and other vehicle control plan. Engineering / Redesign Control Plan > All vehicle must be fitted with seat betts and must be warn for all vehicle more than a must be warn for all vehicle more than a must be warn for all vehicle more than the seat. > Morkers must not travel in a vehicle seat which does not have a seat belt for each seat. > Maximum speed limit on site is 30 km/h. > Roads are inspeed limit on site is 30 km/h. > Roads are inspeed limit on site is 30 km/h. > Eccavators must transport loads as low to the ground as possible. > All mobile plant fitted with roll over protection.
Road Vehicle Operations - Tarping Load	s > Driver falling from vehicle, prime mover and trailers.	 > Driver need to tarp up load. > Drivers need to alight vehicle. > Uneven surfaces 	Significant	Unlikely	14	Not Applicable > All roads must be tarped prior to leaving site. > All vehicles must be fundamentally stable (on level ground) prior to exiting the vehicle via use of tarping area. > Driver vehicle inspections conducted for vehicle condition and tarping.
Roads - Pit Access Road Driving (1/8 Grade) - Driving down pit access road in Heavy Vehicle (> 4.5t)	 Collision with other Vehicle(s) 	> Loss of vehicle control due to vehicle failure.	Catastrophic (Principal Hazard)	Possible	22	Raada and Other o Johly one heasy welkice and trave down the pit access road at any point in time. Is balation Vehicle Operative S1 A vehicle is permitted to pass a slow tracked machine must must make the prior to passing.
Roads - Pit Access Road Driving (1/8 Grade) - Driving up haccess road in Heavy Vehicle (> 4.5t GVM)	> Collision with other Vehicle(s)	> Loss of vehicle control due to vehicle failure.	Catastrophic (Principal Hazard)	Possible	22	Roads and Other Vehicle Operating Areas Management Plan A vehicle is permitted to pass a solve tracked machine, the tracked machine must pull over "stop" to a safe are to enable other vehicle to pass, radio communication used or prior to passing. - Radio communication used to control access to pit access road. - Conduct toolbox meeting daily on expected movements on pit access road. - Conduct toolbox meeting daily on expected movements on pit access road. - Neavy Vehicles accessing road are serviced as per OEM recommendations and vehicles are fitted with emergency brakes. - Daily inspections completed on all heavy vehicles to ensure vehicles are operating correctly, this is interfocked within the operation of the heavy vehicle. - Vehicles have emergency brakes. - Road or correctly this is interfocked this in depricated to ensure road is in a suitable driving condition, road is inspected with idity twelice post and use to - Signs in place reinforcing to drivers pit access road rules.
Roads - Pit Access Road Driving (1/8 Grade) -	 Heavy vehicle loss of traction. 	 Road failure due to rain event. Road failure due to strata failure 	Significant	Possible	10	Roads and Other > Post any rain event a light vehicle shall inspect the road for any possible loss of Administrative Vehicle Operating Areas traction issues for a heavy vehicle.

Roads - Pit Access Road - Driving (1/8 Grade) - General access to pit access road.	Collision of vehicle(s) utilising pit access road.	> Pit access road is 1/8 grade which can mark stopping suddenly difficult.> Road has blind corners and potential for fog / twilight / night to hinder vision.	Catastrophic (Principal Hazard)	Possible	22	Roads and Other Vehicle Operating Areas Management Plan	> Single way traffic only on pit access road. > Light vehicles fitted with flashing lights and whip flags. > Vehicle head lights shall be on. > All vehicles accessing pit access road must communicate via radio at the following call points. The intersection, the cutting, the SS's, the top bend and bottom of the hill (channel 27). > All people driving vehicles on site must hold a C class drivers licence and have the relevant qualifications / approvals on site to drive certain heavy vehicles.	Isolation	Significant	Unlikely	14	> Ensure all signs on pit access road reflect controls. > Ensure controls are in applicable inductions
Roads - Pit Access Road - Driving (1/8 Grade) - Light vehicle (<4.5t GVM) accessing pit access road.	> Collison with other Vehicle (Due to Loss of Control)	> Loss of vehicle control due to operator loss of control	Catastrophic (Principal Hazard)	Possible	22	Roads and Other Vehicle Operating Areas Management Plan	> Light vehicles must not drive faster than 30km/h when on roads within the quarry. > Light vehicles must not iterater with heavy vehicles on the pit access road. > Großuct toolbox meeting daily on expected movements on pit access road. > Radio communication used to control access to pit access road. > Jught Vehicles accessing road are serviced as per DEM recommendations and vehicles are fitted with emergency brakes (Hand Brake). > Pit access road is fitted with movimous, half the wheel height of the largest vehicle. > Signs in place reinforcing to drivers pit access road arules.	Engineering / Redesign	Serious	Unlikely	9	> Ensure all signs on pit access road reflect controls. > Ensure controls are in applicable inductions
Roads - Pit Access Road - Driving (1/8 Grade) - People conducting work or pedestrians accessing Pit access road	Collision with Pedestrian	 > Person walking along pit access road. > Person needing to contact work on pit access road. 	Significant	Possible	18	Roads and Other Vehicle Operating Areas Management Plan	> No person(s) are permitted to walk up/down pit access road. > Radio communication used to control access to pit access road. > If work to take place on pit access road, must be done so via work permit. > High visibility clothing worn.	Elimination	Significant	Rare	10	
Roads - Pit Access Road - Driving (1/8 Grade) - Uncontrolled vehicle at intersection from pit access.	Vehicle unable to stop at bottom of 1/8 grade road., collision with other vehicle.	> Traveling two fast, not using gearing. > Failure of vehicle	Catastrophic (Principal Hazard)	Unlikely	19	Roads and Other Vehicle Operating Areas Management Plan	 Road design incorporates a bend for emergency run off, including material to stop uncontrolled moving vehicle. Easily able to see oncoming vehicle (hazards) uncontrolled coming down hill. Reatric Heavy whicle movements in poor road / weather conditions. Warning devices on all vehicles (horn). Vehicles maintained as per OEM spec and other relevant industry communications. Pre-stait inspections completed every morning on all vehicles, including brake function test. And emergency steering. 	Engineering / Redesign	Significant	Unlikely	14	
					0						0	
					0				-	1	0	
					0						0	
					0						0	
					0						0	
					0						0	
					0						0	
					0						Ů	
					0						0	





SAFETY MANAGEMENT SYSTEM

HTA-S-HSE-057

Hy-Tec Industries – Austen Quarry

"Uncontrolled Copy When Printed"

Appendix 19B PPE Matrix

PERSONAL PROTECTIVE EQUIPMENT Note: PPE use is a "minimum" risk control measure, however it can be used in conjunction with other safety controls. LEGEND- M= Mandatory R = Recommended if required SITE SPECIFIC RULES WILL DETERMINE WHAT PERSONAL PROTECTIVE EQUIPMENT (PPE) MUST BE WORN												
PPE Type Hazard/Activity	HEAD PROTECTION MUST BE WORK Safety Helmet	HEARING PROTECTION HEARING PROTECTION	Eye Protection	FOOT PROTECTION MUST BE WORN Safety Boots	PROTECTIVE CLOTHING MUST BE WORK Long Clothing	HAND PROTECTION MUST BE WORN Hand Protection	SAFETY VEST MUST BE WORN Hi-Vis Clothing	Respiratory Equipment	Face SHIELD MUST BE WORN Face Shield	WELDING MASK WUST BE WORN Welding Mask	SAFETY HARNESS MUST BE WORN Safety Harness	
Employees/visitors	М	R	M	М	М		М					
Plant Operation	М	М	М	М	М	R	М	R	R			
Mechanical Maintenance	М	R	М	М	М	R	М	R	R		R	
Fabrication Work	M	М	М	М	М	М	М	R	R	R	R	
Hazardous Substances	М	R	М	М	М	М	М	R	R			
Workshop Activities	М	M	М	М	М	R	М	R	R	R		
Office Work				М	М		М					
Working at Heights	М	R	М	М	М	R	М	R	R	R	М	
Confined Spaces	М	М	М	М	М	R	М	R	R	R	R	
Cleaning Activities	М	R	М	М	М	R	М	R	R		R	

Status: APPROVED	Owner: HSE Manager	Doc: HTA-S-HSE-057	Rev: 0.0	Issued: 13 Sep 2012	Page 1 of 1
Otatus. ATTROVED	Owner. HSE Manager	Doc. 111A 5 115E 057	1100.0.0	1550Cu. 15 5Cp 2012	Tuge I OF I

PIRMP Document Control

Adelaide Brighto

Austen Quarry

	Pollution Incident Response Management Plan Review Sheet										
Plan	Revision No	Date	Review	Approved by (Planning and Development)							
PIRMP	1.0	08.03.2013	Reviewed – no changes	D.Thiedeke							
PIRMP	1.0	15.05.2014	Reviewed – minor changes made	D.Thiedeke							
PIRMP	2.0	04.05.2015	Reviewed – update contacts	D.Thiedeke							
PIRMP	3.0	12.05.2016	Reviewed – no changes	D.Thiedeke							
PIRMP	4.0	09.05.2017	Reviewed – update contacts	D.Thiedeke							
PIRMP	5.0	11.05.2018	Reviewed – no updates	D.Thiedeke							
PIRMP	6.0	08.03.2019	Alterations to numerous sections	D.Thiedeke							
PIRMP	7.0	27.08.2019	Format changes	D.Thiedeke							
PIRMP	8.0	21.08.2020	Format changes – PIRMP review	D.Thiedeke							
PIRMP	9.0	16.06.2021	Format changes / S21.2 update / Hazard Register update / Management structure update	D.Thiedeke							
PIRMP	10.0	06.02.2023	Alterations to numerous sections	D.Thiedeke							

Status: Approved	Owner: NP&DM Manager	Doc: SSD 6084	Rev: 1	Issued: 28/08/2015	Page 1 of 1
------------------	-------------------------	---------------	--------	--------------------	-------------